





Fig. 12. Pool boiling with different roughnesses of copper tube at different saturation temperatures.

Table 4
Relationship between external HTC and surface roughness for copper tubes.

Boiling mode	Saturation temperature [°C]	Dependence of external HTC on surface roughness

The falling film HTC's are shown to mostly exhibit similar overall trends to the comparative pool boiling results in Fig. 12 with the HTC displaying a similar sensitivity to increases in heat flux. However, at higher heat fluxes are reached, the falling film HTC's begin to tail off and become less sensitive to increases in heat flux. This is due to the