




Fig. 3. Schematics of test chamber operation modes and temperature and pressure measuring points.