




Fig. 9. Relation between dimensionless h and dimensionless q'' according to the surface roughness.