





Figure 6 SEM images of the sintered boiling surface after pool boiling tests and desoldering.