




(b)

Figure 6. SEM images of the sintered boiling surface after pool boiling tests and desoldering.