


(a) the first step



(b) the second step

Fig. 4. Schematic of fabricating copper nanowires.