

Mounting holes (H1-5) are for M3 screws/bolts and should be drilled at 2.5mm (#39) and tapped at .5mm threads.

WARNING: The tabs on the output transistors Q1-8 are at supply voltage and MUST BE electrically isolated from ground when mounting. The HQ1-8 transistor access holes are also based on M3 and should allow the top of a pan head to pass through but the actual mounting holes should be drilled and tapped based on your mounting hardware and heatsink requirements.