

▲ E 2000 LADDER

what the number means at the press

- **< 1.0** Dead match. Don't chase it.
- **1 – 2** Commercial match. Most jobs pass here.
- **2 – 3.5** Visible side by side. Correct if the client will see both.
- **> 3.5** The client will see it. Correct before you run the job.

▲ COMMON DRIFT → WHAT TO MOVE

when your Lab reading drifts, the fix is almost always one ink

DRIFT (vs. target)	FIRST MOVE	IF STILL OFF
+a (too red)	pull magenta	or add a touch of cyan
-a (too green)	pull cyan	or add a touch of magenta
+b (too yellow)	pull yellow	or add a touch of magenta on warm stock
-b (too blue)	pull cyan	or add a touch of yellow
-L (too dark)	pull K	then pull all four if still heavy
+L (too light)	add CMY proportional	K last, sparingly

▲ FIRST, CHECK THE MATERIAL

You are not printing on white. The substrate shifts every color on it. Before you blame the build, measure the bare stock. If it's cyan, you can't hit warm colors by piling on more ink.
No amount of yellow fixes a cyan substrate. Diagnose where the cast is coming from first.

▲ GRAY BALANCE BUILDS

neutral CMY targets by substrate

COATED (GRACoL)

25%	C 25	M 19	Y 19
50%	C 50	M 40	Y 40
75%	C 75	M 64	Y 64

UNCOATED

25%	C 25	M 18	Y 18
50%	C 50	M 43	Y 43
75%	C 75	M 68	Y 68

GOT A DRIFT? CLOSE IT.

Enter your target, what's on the press, and your material. Drawdown returns the exact CMYK moves.

Free in your browser · drawdown.press