




INA219 SCALING NOTES WRONG







Drew Maatman

Sheet: /+180V Telemetry/ File: pos180_telemetry.kicad_sch


| Title:


 Size: A
 Date: 2023-05-12
 Rev: PRELIM


 KiCad E.D.A. kicad 7.0.1
 Id: 7/21


RICHU L.D.A. KICHU 7.


5






























FIND A CONNECTOR THAT CAN HANDLE HIGH VOLTAGE AND SIGNALLING THAT ISNT AWFUL

CONSIDER USING 0.1" SMT HEADERS

ADD BYPASS



Drew Maatman

Sheet: /IO Connectors/ File: IO Connectors.kicad sch

| Title:

 Size: A
 Date: 2023-05-12
 Rev: PRELIM

 KiCad E.D.A. kicad 7.0.1
 Id: 20/21

