

| 1        | 2   | 7                     | <i>I</i> .                           | 5        |
|----------|---|-----------------------|--------------------------------------|----------|
| 1        | Z   |                       | 4                                    | 5        |
|          |   |                       |                                      |          |
|          |   |                       |                                      |          |
|          |   |                       |                                      |          |
|          |   |                       |                                      |          |
|          | Sheet: +12V Input                                     | Sheet: PGOOD LEDs     |                                      |          |
| A        | Sneet: +12V Input                                     | Sheet: PGOOD LEDS     |                                      |          |
|          | File: POS12_Input.sch                                 | File: PGOOD_LEDs.sch  |                                      |          |
|          | Sheet: +12V Telemetry                                 | Sheet: Status LEDs    |                                      |          |
|          | File: POS12_lelemetry.sch                             | File: Status_LEDs.sch |                                      |          |
|          | Sheet: +3.3V Power Supply                             | 11tc. 5tata5_2255.5cm |                                      |          |
|          |   |                       |                                      |          |
|          | File: POS3P3_Power_Supply.sch                         |                       |                                      |          |
| H        | Sheet: +3.3V Telemetry                                |                       |                                      |          |
|          | File: POS3P3_Telemetry.sch                            |                       |                                      |          |
|          | Sheet: +1.8V Power Supply                             |                       |                                      |          |
|          | File: P051P8_Power_Supply.sch                         |                       |                                      |          |
|          | File: PUS1P8_Power_Supply.sch Sheet: +1.8V, Telemetry |                       |                                      |          |
|          | Sheet: +1.0V  |                       |                                      |          |
| B        | File: POS1P8_Telemetry.sch                            |                       |                                      |          |
| В        | Sheet: PIC32MZ Programming                            |                       |                                      |          |
|          | <br>File: PIC32MZ_Programming.sch                     |                       |                                      |          |
|          | Sheet: PIC32MZ Bypass                                 |                       |                                      |          |
|          | File: PIC32MZ_Bypass.sch                              |                       |                                      |          |
|          | Sheet: PIC32MZ Clocking                               |                       |                                      |          |
|          | Silect: PIC32M2 Clocking                              |                       |                                      |          |
| $\vdash$ | File: PIC32MZ_Clocking.sch                            |                       |                                      |          |
|          | Sheet: PIC32MZ  |                       |                                      |          |
|          | File: PIC32MZ.sch                                     |                       |                                      |          |
|          | Sheet: USB UART Bridge                                |                       |                                      |          |
|          |   |                       |                                      |          |
|          | File: USB_UART_Bridge.sch                             |                       |                                      |          |
|          | Sheet: USB Telemetry                                  |                       |                                      |          |
| C        | File: USB_Telemetry.sch                               |                       |                                      |          |
|          | Sheet: Time of Flight                                 |                       |                                      |          |
|          | <br>  File: Time_of_Flight.sch                        |                       |                                      |          |
|          | Sheet: POX Sensor                                     |                       |                                      |          |
|          |   |                       |                                      |          |
|          | File: POX_Sensor.sch                                  |                       |                                      |          |
| Н        | Sheet: Display  |                       |                                      |          |
|          | File: Display.sch                                     |                       |                                      |          |
|          | Sheet: Pushbuttons                                    |                       |                                      |          |
|          | File: Pushbuttons.sch                                 |                       |                                      |          |
|          |   |                       |                                      |          |
|          |   |                       |                                      |          |
|          |   |                       |                                      |          |
|          |   |                       |                                      |          |
|          |   |                       | Sheet: /<br>File: Pulse_Oximeter.sch |          |
|          |   |                       | Title:                               |          |
|          |   |                       | Size: A Date: 2020-05-02             | Rev:     |
|          |   |                       | KiCad E.D.A. kicad (5.1.4)-1         | ld: 1/19 |
| 1        | 2   | 3                     | 4                                    | 5        |





## NSIDER A SMALLER SOLUTION WITH LOWER OUTPUT CURRE

