

# **EE206: Communications Principles Tutorial**

**Assignment** 5

- 1. A triangular signal  $m(t) = 4\Lambda[(t 6)/2]$  frequency modulates a carrier signal  $f(t) = 100 \cos(2\pi f_c t)$  with  $k_f = 30$  Hz/volt.
  - a. Sketch the instantaneous frequency deviation in hertz for the obtained FM signal.
  - b. Sketch the instantaneous phase deviation in radian for this FM signal.

#### **Solution:**

### a) For a FM signal


$$f_i(t) = f_c + k_f m(t)$$
 Instantaneous carrier frequency deviation,  $\Delta f_i(t)$ 

 $f_c$ : carrier frequency, a constant

 $k_f$ : frequency sensitivity, a constant ( $\underline{Hz/volt}$ ).

 $m(t) = 4\Lambda[(t-6)/2]$  -8+2t 4 6 8 t


Instantaneous frequency deviation:



#### **Solution:**

$$f_{i}(t) = f_{c} + k_{f} m_{t}$$

$$\theta = \int_{0}^{t} 2\pi f_{i}(\tau) d\tau = 2\pi \int_{0}^{t} (f_{c} + k_{f} m_{\tau}) d\tau = 2\pi f_{c} t + 2\pi \int_{0}^{t} k_{f} m_{\tau} d\tau$$



**b)** The phase deviation in radian is obtained by  $\Phi(t) = 2\pi k_f \cdot \int_0^t m(\tau) d\tau$ .


$$\Phi(t) = 0$$
 for  $t < 4$ 

$$\Phi(t) = 2\pi k_f \int_0^t (-8 + 2\tau) d\tau = 60\pi (t^2 - 8t + 16) \quad \text{for} \quad 4 \le t \le 6$$

$$\Phi(t) = 2\pi k_f \int_4^t (-8 + 2\tau) d\tau = 60\pi (t^2 - 8t + 16) \quad \text{for} \quad 4 \le t \le 6$$

$$\Phi(t) = \Phi(6) + 2\pi k_f \int_6^t (16 - 2\tau) d\tau = 240\pi - 60\pi (t^2 - 16t + 60) \quad \text{for} \quad 6 \le t \le 8$$

$$\Phi(t) = 480\pi \text{ for } t > 8$$



- 2. An 18 MHz carrier is frequency modulated by a 400 Hz cosine waveform. If the FM signal has an amplitude of 5 volts and a peak frequency deviation of 30 KHz.
  - a. Write the expression for the obtained FM signal
  - b. Calculate the peak phase deviation in radian for this FM signal
  - c. Calculate the peak frequency deviation and the peak phase deviation if the frequency of the modulating signal is tripled.

#### **Solution:**

**a**)

$$f_i(t) = f_c + k_f A cos(2\pi f t)$$

$$\theta = \int_0^t 2\pi f_i(\tau) d\tau = 2\pi \int_0^t (f_c + k_f A \cos(2\pi f \tau)) d\tau = 2\pi f_c t + 2\pi \int_0^t k_f A \cos(2\pi f \tau) d\tau = 2\pi f_c t + \frac{Ak_f}{f} \sin(2\pi f \tau)$$

$$f_{FM} = A_{FM} \cos\left(2\pi f_c t + \frac{Ak_f}{f} \sin(2\pi f t)\right)$$

$$= 5\cos(36\pi * 10^6 t + 75\sin(800\pi t))$$

$$f_c = 18MHz$$
  
 $f = 400Hz$   
Peak frequency deviation:  $k_f A = 30KHz$   
 $A_{FM} = 5$ 

b)

$$\theta = 36\pi * 10^6 t + 75\sin(2\pi f t)$$

The maximum phase deviation is 75 rad

$$f = 1200Hz$$

**c**)

Peak frequency deviation:  $k_f A = 30KHz$ 

The peck phase deviation:  $\frac{Ak_f}{f} = 25 \text{ rad}$ 

- 3. A message signal  $m(t) = 0.5 \cos(2\pi 1000t)$  phase modulates a carrier signal  $f(t) = 10 \cos(2\pi 10^6 t)$  with modulation phase sensitivity  $k_p = 0.3$  rad/V.
  - a. Write the expression of the obtained PM signal.
  - b. Construct a phasor diagram for this PM signal.
  - c. Re-construct the phasor diagram if  $m(t) = 0.5 \sin(2\pi 1000t)$ .

```
Solution:
```

**a**)

$$f_{PM}(t) = A_c cos \left( 2\pi f_c t + k_p m(t) \right) = 10 cos \left( 2\pi 10^6 t + 0.15 cos (2\pi 1000 t) \right)$$
$$= 10 cos \left( 2\pi 10^6 t \right) cos (0.15 cos (2\pi 1000 t)) - 10 sin \left( 2\pi 10^6 t \right) sin (0.15 cos (2\pi 1000 t))$$


**b**)

$$\beta_p = k_p A_m = 0.15 < 0.2 \implies \text{NBPM}$$

$$sin(0.15cos(2\pi1000t)) \approx 0.15cos(2\pi1000t))$$
  
 $cos(0.15cos(2\pi1000t)) \approx 1$ 

$$\begin{split} f_{NBPM}(t) &= 10 cos \big(2\pi 10^6 t\big) - 1.5 sin \big(2\pi 10^6 t\big) cos (2\pi 1000 t) \\ &= 10 cos \big(2\pi 10^6 t\big) - 0.75 sin \big(2\pi 10^6 t - 2\pi 1000 t\big) - 0.75 sin \big(2\pi 10^6 + 2\pi 1000 t\big) \end{split}$$

## $f_{NBPM}(t) = 10cos(2\pi10^6t) - 0.75\sin(2\pi10^6t - 2\pi1000t) - 0.75\sin(2\pi10^6 + 2\pi1000t)$



$$\sin(x) = \cos(x - \frac{\pi}{2})$$

c)  $f_{NBPM}(t) = 10cos(2\pi 10^6 t) - 1.5sin(2\pi 10^6 t)sin(2\pi 1000 t)$  $=10cos(2\pi 10^6 t) - 0.75cos(2\pi 10^6 t - 2\pi 1000 t) + 0.75cos(2\pi 10^6 + 2\pi 1000 t)$ Resultant  $2\pi f_m t$  $2\pi f_m t$ Carrier

Phase diagram