CNC Router

Patrick Sorn

$Version\ 2.0$

Contents

1	Intr	Introduction Portal 2.1 Spindle X mount																							
2	Por																								
	2.1	Spindle	e X moi	int .																					
		2.1.1	Base P	late																					
		2.1.2	Front 1	Plate																					
	2.2	Spindle	e Y moi	int .																					
		2.2.1	Side P	late .																					
		2.2.2	Rear P	late																					
2.3	2.3	3 Spindle Z Mount																							
		2.3.1	Main .																						
		2.3.2	Upper																						
		2.3.3	Lower																						
		2.3.4	Drill M	Iount																					

1 Introduction

2 Portal

2.1 Spindle X mount

2.1.1 Base Plate




Figure 1: Base Plate.




Figure 2: Base Plate 3D.




Figure 3: Front Plate.




Figure 4: Front Plate 3D.

- 2.1.2 Front Plate
- 2.2 Spindle Y mount
- 2.2.1 Side Plate
- 2.2.2 Rear Plate
- 2.3 Spindle Z Mount
- 2.3.1 Main

KPF-S 20 has been used as linear mount.

- 2.3.2 Upper
- 2.3.3 Lower

Loslager FF12 will be connected to this part.

2.3.4 Drill Mount




Figure 5: Side Plate.




Figure 6: Side Plate 3D.




Figure 7: Rear Plate.




Figure 8: Rear Plate 3D.




Figure 9: Spindle Z Mount - Main.




Figure 10: Spindle Z Mount - Main 3D.




Figure 11: Spindle Z Mount - Upper.




Figure 12: Spindle Z Mount - Upper 3D.




Figure 13: Spindle Z Mount - Lower.




Figure 14: Spindle Z Mount - Lower 3D.




Figure 15: Drill Mount.




Figure 16: Drill Mount 3D.




Figure 17: Drill Mount Support Plate.