OMRON

MEMS Differential pressure Sensor D6F-PH

User's Manual

MEMS Differential pressure Sensor



A288-E1-01

Contents Outline 2 Structure 2 Dimensions 2 Usage5 Recommended tube connection method of D6F-PH......5 6-1. 6-2. Outline of I2C Interface.......7 7-1. 7-2. Access Address Registers (00h – 01h)......9 7-2-1. 7-2-2. Serial Control Register (02h)......9 7-2-3. 7-2-4. 7-2-5. 7-2-6. 7-2-7. 7-3. 7-3-1. 7-3-2. 7-3-3. 7-3-4. 8-1. Register content 18 8-2. 8-3. 8-4. 10-1. 10-2. 11. WARRANTY AND LIMITED LIABILITY.......32

1. Outline

This User's Manual note is intended to demonstrate how to use and interface with Omron's MEMS differential pressure sensor(D6F-PH). It should be noted that this document is intended to supplement the datasheet, which should be referenced when using the sensor.

2. Structure

Fig.1 shows the internal cross-section view of the MEMS differential pressure sensor (D6F-PH). Air will flow from one inlet and out the other passing over the MEMS flow chip surface. The MEMS chip is able to measure the airflow as air passes over the chip.




Fig.1 the internal cross-section view of MEMS differential pressure sensor (D6F-PH)

3. Dimensions





Fig.2 Outline dimensions of D6F-PH

4. Principle of Pressure detection

By using a thermal mass flow sensor, Omron's MEMS differential pressure sensor can detect fine changes in differential pressure.







Fig. 3 Principle of differential pressure sensor (a) and relationship between flow rate and differential pressure (b)

5. Features of Product

By using a thermal mass flow method, Omron's MEMS differential pressure sensor is more sensitive compared with that of a conventional differential pressure sensor in the low-pressure range.



Thermal mass flow method

The output of Omron's sensor is proportional to the square root of the gas flow rate through the sensor chip surface.

Conventional method

The output of a conventional sensor is proportional to the square of the gas flow velocity through the main channel.

Fig. 4 Comparison with conventional method and thermal mass flow method

Table1. Specifications of D6F-PHuuuu

Item			Des	cription	
	Min	Тур	Max	Unit	Note
Range of Differential	-50	-	50	Pa	D6F-PH0505AD3
Pressure	0	-	250	Pa	D6F-PH0025AD1
	-500	-	500	Pa	D6F-PH5050AD3
Resolution	-	12	-	bit	
Zero point accuracy (Note)	-0.2	-	+0.2	Pa	
Span accuracy (Note)	-3	-	+3	%R.D.	
Span shift by Temperature	-0.5	-	+0.5	%R.D.	With respect to a change of 10 degC
Response Time	-	33	50	msec	12bit Resolution
Ambient Operating Temp	-20	-	80	degC	without freezing and condensation
Ambient Storage Temp	-40	-	80	degC	without freezing and condensation
Ambient Operating Humidity	35	-	85	%RH	without freezing and condensation
Ambient Storage Humidity	35	-	85	%RH	without freezing and condensation
Supply Voltage	2.3	3.3	3.6	VDC	
Current Consumption	_	-	6	mA	Vcc=3.3V, 25degC
Frequency of SCL	-	-	400	kHz	FAST Mode

(Note) Span accuracy and zero point accuracy are the independence errors, and are not satisfied at the same time.

6. Usage

6-1. Recommended tube connection method of D6F-PH

When connecting the D6F-PH sensor in a bypass configuration, the sensor is able to detect fine pressure changes. This is achieved by providing an orifice in the main channel, which generates a small pressure change before and after the orifice. The D6F-PH will be connected to the bypass flow path from the pressure port which is provided before and after the orifice.




Fig. 5 Recommended tube connection method of D6F-PH

Here, the inner diameter of the bypass tube which is connected to the D6F-PH is 4[mm] and its length is 800[mm] or less.

6-2. Electrical connection method of D6F-PH

For the I2C output, the D6F-PH will require a pull-up resistor to each clock line(SCL) and data line (SDA). A pull-up resistor of $2.2[k\,\Omega]$ (recommended value) should be implemented between the Vcc as shown in Fig.6. In addition, please adjust the pull-up resistor's value depending on the transfer rate of SCL and the I2C wire length.




Fig. 6 Electrical connection method of D6F-PH

* Precautions when connecting the flow sensor

An error may occur during communications due to the effect of the noise of the customer's environment. In such a case, check the following points, and correct the communications error.

(1) Checking the communications speed

This product supports an SCL frequency of up to 400 kHz, however, if there is a likelihood of occurrence of a communications error, we recommend using the SCL frequency at 100 kHz.

(2) Checking the wiring cable

If the length of the cable used to connect the customer-controlled microcontroller and an OMRON flow sensor is long, the effect of noise may be more prominent. In such a case, OMRON recommends using a shielded cable.

(3) Checking the pull-up resistor's value

A pull-up resistor is necessary for I2C communications of this product. Although the recommended resistor value is $2.2[k\Omega]$, please select the optimum resistor value according to the length of the cable used to connect the customer-controlled microcontroller and the OMRON flow sensor. A communications error is judged unless an ACK is returned from the sensor side. The ACK response time is equal to one clock cycle of SCL. If an ACK response is not returned after this time has elapsed, it results in a communications error. In such a case, turn off the device.

7 Specification of Communication

7-1. Outline of I2C Interface

Table2. Basic specification of I2C communication

		D6F-PH0025AD1	D6F-PH0025AD1-1	D6F-PH0025AD1-2	D6F-PH0025AD1-3				
		D6F-PH0505AD3	D6F-PH0505AD3-1	D6F-PH0505AD3-2	D6F-PH0505AD3-3				
		D6F-PH5050AD3	D6F-PH5050AD3-1	D6F-PH5050AD3-2	D6F-PH5050AD3-3				
Communication method		I2C							
Slave	HEX	0x6C	0x6D	0x6E	0x6F				
Address	BIN (7bit)	110_1100	110_1101	110_1110	110_1111				
	inications uency	Max. 400k Hz							
Signal	SCL	Serial Clock							
	SDA		Data Signal						

Table 3. I2C slave address is expressed as below. (Example of 0x6C)

Bit	Bit 7	Bit 6	Bit 5	Bit 4	Bit 3	Bit 2	Bit 1	Bit 0
								R/W
Value	1	1	0	1	1	0	0	1/0

During Write: Set LSB of slave address to "0" to form D8h (1101_1000b). During Read: Set LSB of slave address to "1" to form D9h (1101_1001b).

7-2. Interface Configuration Registers

The memory and registers access are controlled by writing to the interface configuration registers.

Signal Digital Processing

I2C

Configuration Register

A/D converter

Table4. Internal Register Map

Address Register name Descriptions

D040h SENS_CTRL Sensor Control Register

R	Register
D046h FLAGS FI	lag Register
_	CRC Calculation Control
D051h COMP_DATA1_H C	Compensated Flow
D052h COMP_DATA1_L ra	ate Register
D061h TMP_H In	nternal Temperature
D062h TMP_L R	Register
D065h REF_FLOW1_H S	Sensor Reference
D066h REF_FLOW1_L FI	low Register
D067h THRESH_FLOW1_H S	Sensor Threshold
D068h THRESH_FLOW1_L FI	low Register

Various internal registers

In case access to internal registers are needed, the target register's address needs to be set to the Interface Configuration Register (address:00h and 01h).




Fig. 7 Configuration overview

Table5. Interface Configuration Register Map

Configuration Address	Function	Note
00h	Access Address 1 (Upper byte)	Upper byte of first Access Address
01h	Access Address 2 (Lower byte)	Lower byte of first Access Address
02h	Serial Control	Write / Read Access Control
03h	Write Buffer 0	Data to be written at Address
04h	Write Buffer 1	Data to be written at Address + 1
05h	Write Buffer 2	Data to be written at Address + 2
06h	Write Buffer 3	Data to be written at Address + 3
07h	Read Buffer 0	Data read from Address
08h	Read Buffer 1	Data read from Address + 1
09h	Read Buffer 2	Data read from Address + 2
0Ah	Read Buffer 3	Data read from Address + 3
0Bh	Initialize	
0Dh	Power Sequence	Hardware reset control

Upper byte: bit[15:8] of 16bit data, Lower byte: bit[7:0] of 16bit data

7-2-1. Access Address Registers (00h – 01h)

The access address registers are used to access internal register blocks including sensor register map, ADC register map, and internal memory. It specifies the data transfer start address with auto increment for multiple byte data transfer.

Table6. Access Address Register

4	Address	MSB D7	D6	D5	D4	D3	D2	D1	LSB D0
	00h	A15	A14	A13	A12	A11	A10	A9	A8
Г	01h	A7	A6	A5	A4	A3	A2	A1	A0

7-2-2. Serial Control Register (02h)

Table7. Serial Control Register (02h)

The serial control register contains various bits to modify the behavior of the serial access.

Address	MSB D7	D6	D5	D4	D3	D2	D1	LSB D0
02h	D_byte_ cnt[3]	D_byte_ cnt[2]	D_byte_ cnt[1]	D_byte_ cnt[0]	Req	R_WZ	Acc_ctl2 [1]	Acc_ctl2 [0]

- Acc_ctl2 [1:0] Access Control bits
 - 0 0 = 16bits address (A15-A0) access (internal ROM and registers)
 - 0 1 = 8bits address (A7-A0) access and used to access MCU internal 256 byte dual port RAM.
 - 1.0 = reserved
 - 11 = reserved
- R WZ Read or Write access select bit
 - 0 = Write Access
 - 1 = Read Access
- Req- Request bit
 - 0 = the previous request is done
 - 1 = new request. After the serial bus bridge controller finishes a request, it will clear Req to 0. For write requests the bridge controller moves the data in write data buffers to the location pointed by access address. For read requests the bridge controller stores the read data into data buffer.
- D byte cnt3 [3:0]

Transfer data byte count. It only supports 1, 2, 3, 4 data byte transfer.

7-2-3. Write Buffer Registers (03h – 06h)

There are four write data buffer registers at address: 03h – 06h. To perform a write, the host can either use a single command or perform separate writes to the following addresses.

The host can write to sensor register map in single byte transfer:

The host can burst write data start from address = 00h with following data byte, A[15:8], A[7:0], 18h, data[0].

Or the host can do four serial bus writes and write one data byte into serial bus register with the following steps.

- •Write A[15:8] to address = 00h of interface configuration registers.
- •Write A[7:0] to address = 01h of interface configuration registers.
- •Write data[0] to address = 03h of interface configuration registers.
- •Write 18h to address = 18h of interface configuration registers.(1byte, new request, write) [Note] Read Serial Control register(02h). If Req = 0 (02h[3]), controller is finished with write.

7-2-4. Read Buffer Registers (07h – 0Ah)

There are four read data buffer registers at address: 07h - 0Ah. To perform a read, the host can either use a single streaming command or perform separate commands to the following addresses. After the read request is done by the internal serial bus bridge controller, the Req bit is cleared to 0 and read data is stored in rd_buf1 - rd_buf4 (address = 07h - 0Ah).

For single byte read request the host can burst write A[15:8], A[7:0], 1Ch at start address = 00h. The host needs to read the command register until the Req bit is cleared to 0, then read "read data buffer" for read data at address = 07h.

The host can perform a single byte read by individually programming the following registers.

- •Write A[15:8] to address = 00h of interface configuration registers.
- •Write A[7:0] to address = 01h of interface configuration registers.
- •Write 1Ch to address = 02h of interface configuration registers.(1byte, new request, read) [Note] Read address = 02h. If Req = 0 (02h[3]), controller is finished with read data[0] from address = 07h.

7-2-5. Initialize (0Bh)

Initialization process after the device is turned on. Initialization must be performed to load the trimming data of NVM.

Write 00h in the initialization register (0Bh)

For details, refer to Section 7-2-7. Example of I2C Access Commands.

7-2-6. Power Sequence Register (0Dh)

Table 8. Power Sequence Register (0Dh)

Address	MSB	DO	DE	D.4	DO	Da	D4	LSB
	D7	D6	D5	D4	D3	D2	D1	D0
0Dh	Hard_Rese t	ADC_state	ADC_state	ADC_state	Pwr_seq_s tate5	Pwr_seq_st ate5	Pwr_seq_st ate5	Pwr_seq_st ate5

Table 9. Details of Power Sequence Register

Bit	Name	R/W	Description Description
DIL	Name	FX/ V V	Description
[3:0]	Pwr seg state5	R	Indicates the state of the power sequence.
			h0(0000b): Idle
			h2(0010b): Active
			h9(1001b): Execute
[6:4]	ADC_state	R	State in which ADC is controlled
[7]	Hard_Reset	R/W	1-> Hardware reset is performed (Automatically
	_		cleared after execution)
			0-> Hardware reset is not performed

The state is h0 after the initialization process, or when the power supply is reset.

The state is h2 when 06h is written in D040.


The state is h9 during the operation.

When a hardware reset is performed, the hardware reset bit is automatically cleared to "0" after the execution of reset, the internal register returns to the default value, and the internal trimming value is reloaded from the non-volatile memory. This hardware reset function is similar to the power reset function.

Notes

· When using hardware reset, set bits 0 to 6 to "0".

7-2-7. Example of I2C Access Commands



7-3. Description of Registers

The internal memory and registers of the sensor module can be accessed via the interface configuration registers.

7-3-1. Sensor Control (D040h)

Table10. SENS_CTRL

Address	MSB							LSB
Addicss	D7	D6	D5	D4	D3	D2	D1	D0
D040h						MS	DV_PWR[1]	DV_PWR[0]
Write Access	None	None	None	None	None	Host & MCU	Host & MCU	Host & MCU
Default	0	0	0	0	0	0	0	0

- DV_PWR[1:0] Main Device power mode setting
 - 0.0 = Standby All blocks are powered down.
 - 1 0 = MCU on Used when only MCU is required. Basic analog and memories are powered on and MCU clock is running.

Note: This register should not be changed during a measurement.

- MS MCU start Begin execution of measurement or MCU mode based on the state of DV_PWR.
 - 0 = Stop

Sequences are stopped and MCU clock is turned off.

• 1 = Start

The MCU clock is started and the MCU mode is executed.

7-3-2. Flags (D046h)

Table11. FLAGS

Address	MSB							LSB
Address	D7	D6	D5	D4	D3	D2	D1	D0
D046h					OS1		HV1	SV
Write Access	None	None	None	None	Host & MCU	None	Host & MCU	Host & MCU
Default				0	0	0	0	0

- SV Supply Voltage (VDD) Flag
 - 0 = Supply voltage is within specification.
 - 1 = Supply voltage is outside of specification.
- HV1 Heater Voltage Flag
 - 0 = Heater voltage is within specification.
 - 1 = Heater voltage is outside of specification.
- OS1 Open Sensor Flag
 - 0 = Sensor is connected.
 - 1 = Sensor is not connected.
- HV2 and OS2 are reserved bits. In case of write access, you should set to "0".

^{*} If you want to read flag register, it is recommended to read twice in order to avoid conflict with the MCU update.

7-3-3. CRC Calculation Control (D049h)

Table 12. INT_CTRL

ADDR	MSB							LSB
ADDIX	D7	D6	D5	D4	D3	D2	D1	D0
D049h							CRC_EN	
Write Access	NONE	NONE	NONE	NONE	NONE	NONE	Host& MCU	NONE
Default	0	0	0	0	0	0	1	0

- CRC_EN CRC check calculation enable (See below for more information about the CRC)
 - 0 = CRC check calculation disable
 - 1 = CRC check calculation enable

Description of the CRC calculation

CRC Overview

The CRC is used as an error detection method in a data communication. Our flow sensor use the CRC8 polynomial $x^8 + x^5 + x^4 + 1$. The following is an example of I2C access 2 byte read using CRC function.





Fig.8 Example of 2byte read with CRC

- Bit unit CRC-8 calculation method
- 1. The data bit sequence will be aligned in a line.
- 2. The polynomial bit string will be aligned under the line of the data bit sequence.
- 3. If the data bit above the leftmost the polynomial bit sequence is 0, the polynomial bit sequence is shifted one bit to the right. If the data bit above the leftmost polynomial bit sequence is 1, the data bit and the polynomial bit are calculated by XOR. Then the polynomial bit sequence are shifted one bit to the right.
- 4. 1-3steps are repeated until the polynomial bit sequence reaches the right end of the data bit sequence.

The following example shows how to calculate the CRC byte based on XOR calculation.

	hex	bin
1st Byte of data	04h	00000100
2nd Byte of data	02h	00000010
Polynomial $(x^8 + x^5 + x^4 + 1)$	131h	100110001
CRC-byte checksum	225h	11100001



Polynomial bit sequence

Fig.9 XOR operation example of CRC-8

7-3-4. Data Registers (D051h-D068h)

Table13. 16bit Data Register Map

Address	Registers Name	MSB D7	D6	D5	D4	D3	D2	D1	LSB D0	Description		
D051h	COMP_DATA1_H	DATA<15:8>					DATA<15:8>					Compensated Flow rate
D052h	COMP_DATA1_L	DATA<7:0>							Register			
D061h	TMP_H		DATA<15:8>				Internal Temperature					
D062h	TMP_L	DATA<7:0>							Register			

For additional information, please refer to Section 8: Explanation of output data.

8. Explanation of output data

The measured data is sent to the dedicated registers. These registers contain, respectively, upper byte and lower byte of the sensing signals of the sensor.

For example, the compensated flow data is given by the concatenation COMP_DATA1_H & COMP_DATA1_L in unsigned 16bit number. And the raw flow data is given by the concatenation UCFM1_H & UCFM1_L and it is expressed as a 2's complement of signed 16bit number.

8-1. Data alignment

Sensing data is represented as 16bit numbers. The data is split and sent in two consecutive bytes to Flow Registers in "Big Endian" format.

"Big Endian" means that the upper byte of the number is stored in a register at the lowest address, and the lower byte at the highest address.

8-2. Register content

- •COMP_DATA1_H & COMP_DATA1_L [D051h D052h] : Compensated Data (unsigned) These registers contain compensated flow rate data.
 - O If pressure range is ± 50 [Pa] or ± 500 [Pa]

$$Dp[Pa] = (Pv - 1024)/60000*RANGE - RANGE/2 (RANGE = 100 or 1000)$$

Where, Pv is Register content stored in the Compensated Flow Data registers [D051h – D052h].

O If pressure range is 0-250[Pa]

$$Dp[Pa] = (Pv - 1024)/60000*RANGE (RANGE = 250)$$

Where, Pv is Register content stored in the Compensated Flow Data registers [D051h – D052h].

•TMP_H & TMP_L [D061h – D062h] : Temperature data (signed)

The values stored in these registers represent the temperature data measured by the internal temperature of the ASIC.

The following formula can be applied to convert register data into temperature value.

$$Tv \ [^{\circ}C] = (Rv - 10214) / 37.39$$

Where, Tv is Converted temperature value in the degC format, and Rv is Register content stored in the Temperature Data register.

Note: Temperature data is for reference ONLY. Its accuracy is not specified in the device specifications.


8-3. Example of Sensing data

The below tables provide a few basic examples of the data that is read in Flow Sensor Registers when the device is subject to given flow and temperature. The values listed in the tables are given under the hypothesis of perfect device calibration (i.e. no offset, no gain error, etc).

Table 14. Temperature Data registers content vs. Temperature value

Address of	Registers	Value of	Registers	Converted
TMP_H	TMP_L			Temperature values
D061h	D062h	HEX DEC		
2Bh	8Dh	2B8Dh	11149	25.0 degC
2Eh	FFh	2EFFh	12031	48.6 degC
26h	BBh	26BBh	9915	-8.0 degC

8-4. Sensor Operation flow chart



*1 If you use CRC function, please send some command refer to Page.17.

Fig.10 Flowchart of Sensor operation

Communication time

Item	Sign	Remarks
Response time	α	$\alpha \ge 33 \text{ ms}$
Sampling interval	β	β > α




Fig.11 Time axis image view of the differential pressure measurement

9. I2C Instruction for Sensor Operation

1. Initialization after power up [Must be done]

Issue this command 200 µs after turning on the power.

I2C command: The device must be unlocked then write 0x00 to the EEPROM Control Register(0xB) to load NVM trim values, but keep the MCU in non-reset state.

START	Slave Address	ACK	Access Address	ACK	Write Data	ACK	STOP
S	D8h (6Ch (7b)+ 0)	Α	0Bh	Α	00h	Α	Р

2. Execute MCU mode after desired configuration registers

Writing 06h to the Sensor Control Register (D040h) will execute the MCU mode outlined in Section 6 with the configured setting for the ADC Resolution and Gain, Compensation. Reading the Sensor control register after writing a 06h will show the MUX selection chosen by the MCU. After running the process, MS bit will be set to "0".

[Caution]: Do not read or write to the Device while the MCU is executing. It would be safe to read/write only after 33ms.

I2C command: Write 06h to the Sensor Control Register (D040h) (MS=1&MCU_on)


START	Slave Address	ACK	Access Address	ACK	Reg Address H	ACK	Reg Address L	ACK
S	D8h (6Ch (7b)+ 0)	Α	00h	Α	D0h	Α	40h	Α

√	Serial Ctrl	ACK	Write Data	ACK	STOP
	18h	Α	06h	Α	Р

3. Reading the Upper and Lower byte of Compensated Flow Data Registers(D051h & D052h) The first data after the initialization process is not the flow rate data. Disable this data.

I2C command: To read Compensated flow data register, it needs to set 2Ch (it means 2byte read) to interface configuration register (address:2h).

START	Slave Address	ACK	Access Address	ACK	Reg Address H	ACK	Reg Address L	ACK
S	D8h (6Ch (7b)+ 0)	Α	00h	Α	D0h	Α	51h	Α



I2C command: Through Read Buffer 0(address:07h) and Read Buffer 1(address:08h), you can read the 2byte of Compensated flow data.

START	Slave Address	Slave Address ACK Access Address		ACK	\vdash
S	S D8h (6Ch (7b)+ 0)		07h	Α	J) '
					<u>-</u> ,

	Re-Start	Slave Address	ACK	Read Data H	ACK	Read Data L	ACK	STOP
>	RS	D9h (6Ch (7b)+ 1)	Α	xxh	Α	xxh	NA	Р

4. Enable CRC Function

1. Set to "1" to bit[1] of the CRC control register.

I2C command: Write 02h to the CRC Control Register (D049h).

	START	Slave Address	ACK	Access Address	ACK	Reg Address H	ACK	Reg Address L	ACK	
ſ	S	D8h (6Ch (7b)+ 0)	Α	00h	Α	D0h	Α	49h	Α	

Serial Ctrl	ACK	Write Data	ACK	STOP
18h	Α	02h	Α	P

5. Execute Hardware Reset

1. Set to "1" to bit[7] of the Power Sequence register.

I2C command: Write 80h to the Power Sequence Register (0Dh).

START	Slave Address	ACK	Access Address	ACK	Write Data	ACK	STOP
S	D8h (6Ch (7b)+ 0)	Α	0Dh	Α	80h	Α	Р

The hardware reset after the execution, bit 7 is cleared to "0" automatically.

10. Sample Source Code

The following is a sample source code of the D6F-PH control in the case of using STM32microcontroller. The I2C control unit will need to be adjusted to whatever microcontroller is used.

10-1. D6F_PH_Sample.h

```
/* D6F-PH Digital Flow Sensor Header File (using STM32)
* : Copyright: (C) OMRON Corporation, Microdevice H.Q.
* : Auther
* : Revision: $Rev$
* : Id:
              $Id$
* :Date:
              $Date$
* All Rights Reserved
* OMRON Proprietary Right
/* for General
/*=======
                        // for 7bit Slave Address
#define SA 7
                  0x6C
//#define RANGE_MODE 100 // Full Range +/-50[Pa]
                                                     Please change the RANGE_MODE
#define RANGE_MODE 250 // Full Range 0-250[Pa]
                                                     define for your target Product
//#define RANGE MODE 1000 // Full Range +/-500[Pa]
                                                     Pressure range.
/*=======*/
/* for Measure Mode
/*=======*/
#define P
              1 // Pressure mode
              2 // Temperature mode
#define T
/* Function prototypes -----
void Initialize( void );
short Press_meas( void );
short Temp meas (void);
/* Private Functions ---
     I2C_WR (unsigned char add, char *dbuf, unsigned char n);
uint8_t I2C_RD_8 (unsigned char add, char *dbuf, unsigned char n);
short I2C_RD_16 (unsigned char add, char *dbuf, unsigned char n);
unsigned short I2C_RD_u16(unsigned char add, char *dbuf, unsigned char n);
void I2C1_Init(void);
void I2C1 Start(void);
void I2C1_MastrSel(uint8_t address, uint8_t rw);
void I2C1_AckEn(void);
void I2C1_AckDis(void);
void I2C1 Stop(void);
void I2C1_senddata(uint8_t data);
uint8_t I2C1_rcvdata(void);
```

10-2. D6F_PH_Sample.c

```
/* D6F-PH Digital Flow Sensor Sample Code (using STM32)
* : Copyright: (C) OMRON Corporation, Microdevice H.Q.
* : Auther
 * : Revision: $Rev$
          $Id$
 * :Id:
 * :Date:
             $Date$
* All Rights Reserved
 * OMRON Proprietary Right
#include "stm32f10x_i2c.h"
#include "D6F_PH_Sample.h"
#define I2C1_SCL_PIN
                                   GPIO_Pin_6
#define I2C1_SDA_PIN
                                   GPIO_Pin_7
#define I2C2_SCL_PIN
                                   GPIO_Pin_10
#define I2C2 SDA PIN
                                   GPIO Pin 11
typedef unsigned char uint8;
typedef unsigned short uint16;
typedef unsigned long uint32;
        short RD_FIFO; /* 16bit data width */
unsigned short uRD_FIFO; /* 16bit data width */
        uint8_t RD_REG; /* 8bit data width */
        char setting_done_flag = 0;
// Dummy wait routine
void adc_wait(volatile unsigned long delay)
       while (delay) delay--;
}
/*=======*/
/* Initialize Function
                                                */
/* Usage : Initialize(void)
                                                */
/* Argument : Null
                                                */
/* Return value : T.B.D
void Initialize( void )
  /* EEPROM Control <= 00h */
```

```
char send1[] = \{0x0B, 0x00\};
   I2C_WR(SA_7, send1, 2);
/* Pressure measure Function
                                                        */
/* Usage
               : Press_meas( void )
                                                        */
/* Argument
               : NULL
                                                        */
/* Return value : Compensated Pressure value (unsigned)
/*=============*/
short Press_meas(void)
   short rd_fifo;
   short rd_flow;
   unsigned long wait_time;
   /* [D040] <= 06h */
   char send2[] = \{0x00, 0xD0, 0x40, 0x18, 0x06\};
   I2C_WR(SA_7, send2, 5);
   wait_time = 33; /*33msec wait */
   /* wait time depend on resolution mode */
   adc_wait(wait_time);
   /* [D051/D052] => Read Compensated Flow value */
   char send3[] = \{0x00, 0xD0, 0x51, 0x20, 0x07\};
   uRD_FIF0 = I2C_RD_u16(SA_7, send3, 5);
   // Press Mode : [Pa] = (xx[count] - 1024) * Full Range [Pa] / 60000 - Full Range [Pa] at
other
        if (RANGE\ MODE == 250) {
           rd_flow = ((rd_fifo - 1024) * RANGE_MODE *10/60000); /* convert to [Pa] */
        }
        else {
           rd_flow = ((rd_fifo - 1024) * RANGE_MODE *10/60000) - RANGE_MODE*10/2; /* convert
to [Pa] */
   return rd_flow;
/* Temperature measure Function
                                                        */
/* Usage
               : Temp_meas()
                                                        */
/* Argument
               : NULL
                                                        */
/* Return value : x10 Temperature
                                                        */
```

```
short Temp_meas(void)
  short
           rd temp;
  unsigned long wait_time;
  /* [D040] <= 06h */
  char send2[] = \{0x00, 0xD0, 0x40, 0x18, 0x06\};
  I2C_WR(SA_7, send2, 5);
  /* wait time depend on resolution mode */
  wait_time = 33; /* 33msec wait */
  adc_wait(wait_time);
  /* [D061/D062] => Read TMP_H/TMP_L value */
  char send3[] = \{0x00, 0xD0, 0x61, 0x20, 0x07\};
  RD_FIFO = I2C_RD_16 (SA_7, send3, 5);
  rd_{temp} = ((RD_{FIF0} - 10214) * 1000 / 3739); // convert to degree-C(x10)
  return rd_temp;
}
/* Public Basic Functions -----
/*=======*/
/* I2C Write command
                                                */
/* Usage : I2C1_WR()
/* Argument : 7bit Slave Address(char)
/*
/* Return value : 8bit Read result
int I2C_WR(unsigned char add, char *dbuf, unsigned char n) {
  int i = 0;
                         /* Start condition */
  I2C1_Start();
  I2C1_MastrSel(add, 0); /* Slave Address
                                              */
  while (n--)
    I2C1_senddata(dbuf[i]); /* Send Data
    j++;
                         /* Stop condition */
  I2C1 Stop();
  return 0;
/* I2C Read command
                                                */
         : I2C_RD()
/* Usage
             : char add (7bit Slave Address)
/* Argument
/*
                char *dbuf (Write data)
/*
                unsigned char n (Number of bytes)*/
```

```
unsigned char n (Number of bytes)*/
/* Return value : 8bit Read result
uint8_t I2C_RD_8 (unsigned char add, char *dbuf, unsigned char n) {
   int i = 0;
  char n_w;
  n_{w} = n - 1;
   /* I2C Pre-WR Access */
   I2C1_Start();
                           /* Start condition */
   I2C1_MastrSel(add, 0); /* Slave Address 7bit => 8bit */
  while (n_w--) {
    I2C1_senddata(dbuf[i]); /* Send Data
                                               */
    j++;
                           /* Stop condition */
   I2C1_Stop();
  /* I2C RD Access */
   I2C1_Start();
                           /* Start condition */
   I2C1_MastrSel(add, 0); /* Slave Address 7bit => 8bit */
   I2C1_senddata(dbuf[n-1]); /* Word Address
                           /* Re-Start condition */
   I2C1_Start();
   I2C1_MastrSel(add, 1);
                           /* Slave 7bit \Rightarrow 8bit for RD */
                           /* ack diable for 1 byte */
   I2C1_AckDis();
   I2C1_Stop();
                           /* Stop condition send */
  RD_REG = I2C1_rcvdata(); /* Read Data */
   return RD REG;
/* I2C Read command
         : I2C RD 16()
/* Usage
                                                 */
               : char add (7bit Slave Address)
/* Argument
                                                 */
/*
                 char *dbuf (Write data)
/*
                 unsigned char n (Number of bytes)*/
/* Return value : 16bit Read result
short I2C_RD_16 (unsigned char add, char *dbuf, unsigned char n) {
   int i = 0;
  char n w;
  uint8_t rd_fifo[2] = {0, 0};
  n w = n - 1;
   /* I2C Pre-WR Access */
   I2C1 Start();
                              /* Start condition */
   I2C1_MastrSel(add, 0);
                            /* Slave Address 7bit => 8bit */
  while (n_w--) {
    I2C1_senddata(dbuf[i]); /* Send Data
```

```
j++;
                             /* Stop condition */
  I2C1_Stop();
  adc_wait(5); /* 5msec wait */
  I2C1_Start();
                             /* Start condition */
  I2C1_MastrSel(add, 0); /* Slave Address 7bit => 8bit */
  I2C1_senddata(dbuf[n-1]);
                             /* Word Address
                                              */
                             /* Re-Start condition */
  I2C1_Start();
                         /* Slave 7bit => 8bit for RD */
  I2C1 MastrSel(add. 1);
  I2C1_AckEn();
                             /* ack enable send after MSB 1 byte read */
  rd_fifo[0] = I2C1_rcvdata(); /* Read Data */
  I2C1_AckDis();
                             /* ack diable send after LSB 1 byte read */
  I2C1 Stop();
                             /* Stop condition send */
  rd_fifo[1] = I2C1_rcvdata(); /* Read Data */
  RD_FIF0 = ((rd_fifo[0] \iff 8) \mid rd_fifo[1]);
  return RD_FIFO;
}
/* I2C Read command
                                               */
/* Usage
             : I2C RD u16()
                                               */
             : char add (7bit Slave Address)
/* Argument
                                               */
/*
                char *dbuf (Write data)
/*
                unsigned char n (Number of bytes)*/
/* Return value : 16bit Read result
unsigned short I2C_RD_u16 (unsigned char add, char *dbuf, unsigned char n) {
  int i = 0;
  char n w;
  uint8_t rd_fifo[2] = \{0, 0\};
  n_{w} = n - 1;
  /* I2C Pre-WR Access */
                            /* Start condition */
  I2C1_Start();
                          /* Slave Address 7bit => 8bit */
  I2C1_MastrSel(add, 0);
  while (n_w--) {
    I2C1 senddata(dbuf[i]); /* Send Data
    j++;
  I2C1_Stop();
                             /* Stop condition */
  adc_wait(5); /* 5msec wait */
  I2C1_Start();
                             /* Start condition */
```

```
I2C1_Start();
                                /* Re-Start condition */
   I2C1 MastrSel(add, 1);
                                /* Slave 7bit => 8bit for RD */
                                /* ack enable send after MSB 1 byte read */
   I2C1 AckEn();
   rd fifo[0] = I2C1 rcvdata(); /* Read Data */
                                /* ack diable send after LSB 1 byte read */
   I2C1_AckDis();
                                /* Stop condition send */
   I2C1_Stop();
   rd_fifo[1] = I2C1_rcvdata(); /* Read Data */
   uRD_FIF0 = ((rd_fifo[0] << 8) | rd_fifo[1]);
   return uRD FIFO;
}
void I2C1_Init() {
          I2C_InitTypeDef I2C1_InitStructure;
          RCC APB1PeriphClockCmd (RCC APB1Periph I2C1, ENABLE); // start clock of
I2C
          I2C1_InitStructure. I2C_Mode = I2C_Mode_I2C;
          I2C1_InitStructure. I2C_DutyCycle = I2C_DutyCycle_2;
          I2C1_InitStructure. I2C_Ack = I2C_Ack_Enable;
          I2C1_InitStructure. I2C_AcknowledgedAddress = I2C_AcknowledgedAddress_7bit;
          I2C1_InitStructure. I2C_ClockSpeed = 400000;
          GPIO_InitTypeDef GPIO_InitStructure;
                                                                   // make instance of
InitStructure
          RCC_APB2PeriphClockCmd(RCC_APB2Periph_GPIOB, ENABLE);
                                                                   // start clock of GPIO
pins
          GPIO_InitStructure. GPIO_Pin = ( I2C1_SCL_PIN | I2C1_SDA_PIN );
          GPIO_InitStructure.GPIO_Speed = GPIO_Speed_50MHz;
          GPIO_InitStructure.GPIO_Mode = GPIO_Mode_AF_OD;
          GPIO_Init(GPIOB, &GPIO_InitStructure);
          I2C_DeInit(I2C1);
          I2C_Init(I2C1, &I2C1_InitStructure); // Initialize with above parameters
          I2C_Cmd (I2C1, ENABLE);
}
void I2C1_Start() {
          I2C_GenerateSTART(I2C1, ENABLE); // issue start condition
          while(!I2C CheckEvent(I2C1, I2C EVENT MASTER MODE SELECT));
}
void I2C1_MastrSel( uint8_t address, uint8_t RW) {
   uint8_t direct;
   uint32_t event;
   direct = (RW == 0)?I2C_Direction_Transmitter : I2C_Direction_Receiver;
                                   0) ?I2C_EVENT_MASTER_TRANSMITTER_MODE_SELECTED
               =(RW)
                          ==
I2C_EVENT_MASTER_RECEIVER_MODE_SELECTED;
```

```
I2C_Send7bitAddress(I2C1, (address << 1), direct ); //write to Slave
   while(!I2C_CheckEvent(I2C1, event)); // wait ACK
}
void I2C1_senddata(uint8_t data) {
  I2C_SendData(I2C1, data);
                                                                 //transmit the received
command
  while(!I2C_CheckEvent(I2C1, I2C_EVENT_MASTER_BYTE_TRANSMITTED)); // wait ACK
uint8 t I2C1 rcvdata(void) {
  while(!I2C_CheckEvent(I2C1, I2C_EVENT_MASTER_BYTE_RECEIVED)); // wait ACK
  return I2C_ReceiveData(I2C1); // receive 4th 8bit data
void I2C1_Stop() {
  I2C_GenerateSTOP(I2C1, ENABLE); // put stop condition
void I2C1_AckEn() {
  I2C_AcknowledgeConfig(I2C1, ENABLE); // ack enable
void I2C1_AckDis() {
  I2C_AcknowledgeConfig(I2C1, DISABLE); // ack disable
}
```

11. WARRANTY AND LIMITED LIABILITY

Thank you for your usage of products of Omron Corporation ("Omron"). Without any special agreements, this Terms and Conditions shall apply to all transactions regardless of who sells. Place an order, accepting this Terms and Conditions.

1. DEFINITIONS

The following terms used herein have following meaning.

- (1) Omron Products; Electronic components sold by Omron
- (2) Catalogues; Any and all catalogues (including the Components Catalogue), specifications, instructions and manuals relating to Omron Products, including electronically provided data.
- (3) Conditions; Use conditions, rating, performance, operating environment, handling procedure, precautions and/or prohibited use of Omron Products described in the Catalogues.
- (4) User Application(s); Application of Omron Products by a customer, including but not limited to embedding Omron Products into customer's components, electronic circuit boards, devices, equipments or systems
- (5) Fitness; (a)performance, (b) no infringement of intellectual property of third party, (c) compliance with laws and regulations and (d)conformity to various standards by Omron Products in User Applications.

2. NOTE ABOUT DESCRIPTIONS

Please understand following as to contents of the Catalogues.

- (1) Rating and performance is tested separately. Combined conditions are not warranted.
- (2) Reference data is intended to be used just for reference. Omron does NOT warrant that the Omron Product can work properly in the range of reference data.
- (3) Examples are intended for reference. Omron does not warrant the Fitness in usage of the examples.
- (4) Omron may discontinue Omron Products or change specifications of them because of improvements or other reasons.

3. NOTE ABOUT USE

Please understand followings as to your adoption and use of Omron Products

- (1) Please use the product in conformance to the Conditions, including rating and performance.
- (2) Please confirm the Fitness and decide whether or not Omron Products are able to be adopted in the User Application.
- (3) Omron will not warrant any items in 1.(5) (a) to (d) of User Application nor the Fitness.
- (4) If you use Omron Products in the application below, please ensure followings; (i) allowance in aspect of rating and performance, (ii) safety design which can minimize danger of the Application when the product does not work properly and (iii) periodical maintenance of the product and the Application.
 - (a) Applications requiring safety, including, without limitation, nuclear control facilities, combustion facilities, aerospace and aviation facilities, railroad facilities, elevating facilities, amusement facilities, medical facilities, safety devices or other applications which has possibility to influence lives or bodies
 - (b) Applications requiring high reliability, including, without limitation, supplying systems of gas, water and electric power and applications handling right, title, ownership or property, such as payment systems
 - (c) Applications in a harsh condition or environment, including, without limitation, outdoor facilities, facilities with potential of chemical contamination or electromagnetic interference, facilities with vibration or impact and facilities on continual operation for a long period
 - (d) Applications under conditions or environment which are not described in this specification
- (5) Omron Products shown in this catalogue are not intended to be used in automotive applications (including two wheel vehicles). Please DO NOT use the Omron Products in the automotive application.
- (6)THE PRODUCTS CONTAINED IN THIS CATALOG ARE NOT SAFETY RATED. THEY ARE NOT DESIGNED OR RATED FOR ENSURING SAFETY OF PERSONS, AND

SHOULD NOT BE RELIED UPON AS A SAFETY COMPONENT OR PROTECTIVE DEVICE FOR SUCH PURPOSES. Please refer to separate catalogs for OMRON's safety rated products.

4. WARRANTY

Warranty of Omron Products is subject to followings.

- (1) Warranty Period; One year after your purchase
- (2) Warranty; Omron will provide, free of charge, replacements of the same number of malfunctioning products
- (3) Exceptions; This warranty does not cover malfunctions caused by any of the following.
 - (a) Usage in the manner other than its original purpose
 - (b) Usage out of the Conditions
 - (c) Cause which could not be foreseen by the level of science and technology at the time of shipment of the product
 - (d) Cause outside Omron or Omron Products, including force majeure such as disasters

5. LIMITATION ON LIABILITY

THE WARRANTY DESCRIBED IN THIS "TERMS AND CONDITIONS" IS A WHOLE AND SOLE LIABILITY FOR OMRON PRODUCTS. THERE ARE NO OTHER WARRANTIES, EXPRESSED OR IMPLIED. OMRON AND DISTRIBUTORS ARE NOT LIABLE FOR ANY DAMAGES ARISEN FROM OR RELATING TO OMRON PRODUCTS.

6. PROGRAMMABLE PRODUCTS

OMRON shall not be responsible for the user's programming of a programmable product, or any consequence thereof.

7. EXPORT CONTROLS

Buyer shall comply with all applicable laws and regulations of Japan and/or other related countries at the time of export or provision to non-citizens of Omron Products or their technical information.

EC200E

Please check each region's Terms & Conditions by region website.

OMRON CorporationElectronic and Mechanical Components Company

Regional Contact

Americas

https://www.components.omron.com/

Asia-Pacific

https://ecb.omron.com.sg/

Korea

https://www.omron-ecb.co.kr/

Europe

http://components.omron.eu/

China

https://www.ecb.omron.com.cn/

Japan

https://www.omron.co.jp/ecb/