

# SHEETER HOURLY RATE SCHEDULE BY PRODUCT

LOAD	TAKE DOWN
4RLS /1-1/2 HRS	4RLS / 45 MIN
8 RLS / 2HRS	8 RLS / 45 MIN

BUTCHER	KRAFT
30#	250#/HR
40#	1000/HR
50#	750#/HR

DW DRYWAX	FC
ALL	1000#/HR

PLATTER REGULAR	Q2S
ALL	1000#/HR

PLATTER HEAVY	PARCHMENT
ALL	2500#/HR

SILICONE	BROWN WAX
ALL	300#/HR

WET WAX	
60#	1250#/HR
130#	600#/HR
143#	900#/HR

FREEZER	HIGH GLOSS
40#	1500#/HR
45#	2000#/HR

HIGH GLOSS	
40#	2000#/HR
45#	1500#/HR

## Jennerjahn Jumbo Roll Size Change Time

To go down from a 72" to 60"-	30 minutes
To go Up from 48" to 72	15-20 minutes
To go Down from 72" to 54	1 hour—this is difficult & takes more time b/c of paper on back)
To go Down from 60" to 36"	Also difficult & takes an hour or longer