Docusign Envelope ID: 07D426A8-D8D2-43AA-A1A2-8909B8E4A602

Report # 95408

Property Address: **1731 Mountain Blvd. Oakland, CA. 94611**
Inspection Date: **3/16/2026** Inspector: Mike Brooks

261 Spring Street Pleasanton, CA 94566
Tel (925) 249-9611 fax (925) 249-9511
www.specialtyteam.com Lic. 967181

Signed by: 7EEB7B3B666841D... 3/24/2026

Signed by: Suzanne M Peacock 7F8CFDBC33E949F... 3/25/2026

Client Name & Phone: **Alex Tse (925) 788-1432**

Roof Inspection

Scope of Inspection

This report is based on a visual, non-destructive inspection of the roof surface, roof materials used and their application. The report reflects the inspector's observations and opinion of the accessible areas of the roof at the time of inspection. Felt paper under tile roofs is not visible to inspection however is a key component in helping prevent interior water access. Therefore, the condition of the underlayment beneath tile roofs and whether it is intact is unknown and not within the scope of our inspection. The inspection does not include structural problems, termite or dry rot damage, fungus infections or molds. Inspection of the interior or of the attic is not included, unless otherwise noted. We assume no responsibility for any latent defects, manufacturing defects, or any conditions which may occur or become visible after the time of inspection. The inspection and warranty do not include gutters and drainage systems. We can offer an opinion as to their basic function and effect on the roof, however we are not able to determine, in every case, whether seams may leak or if gutters are pitched correctly. Not all conditions that are present may be apparent at the time of inspection. This report has been prepared for the exclusive use of the client and is not transferable.

Roof Description

Roof Type: **Dimensional Asphalt Shingle Roof**

Approx. Age: **5-10 years**

Layers: **One layer**

Approx. Slope(s): **4:12 – 8:12**

Summary of Condition

	Repair Needed	Fair	Repairs Not Needed	N/A		Repair Needed	Fair	Repairs Not Needed	N/A
Roof Field Area	☐	☐	☒	☐	**Vent Pipe Penetration Flashings**	☐	☐	☒	☐
Hip & Ridge	☐	☐	☒	☐	**Chimney Flashings**	☐	☐	☒	☐
Perimeter Flashings	☐	☐	☒	☐	**Skylight Flashings**	☐	☐	☒	☐
Valleys	☐	☐	☒	☐					

Definitions:
Repair Needed - A condition which would, in our opinion, adversely affect water-tight integrity or remaining life of the roof system, unless corrected.
Fair - Although signs of wear and aging were noted, substantial life remains with proper care and maintenance.
Repairs Not Needed - Condition is satisfactory or better and shows signs of little or no wear. No repairs are needed at this time, in our opinion.
N/A - Not Applicable

Please see remarks and recommendations, next page.

Report # 95408

Property Address: **1731 Mountain Blvd. Oakland, CA. 94611**
Inspection Date: **3/16/2026** Inspector: Mike Brooks

Remarks & Recommendations

The asphalt composition shingle roof is within useful service although in need of repair as there are some deficiencies present that may be allowing or can promote interior water incursion if left unattended. The following conditions should be addressed at this time to maintain integrity to the roof and eliminate potential sources of interior water incursion or damage:

1. Overviews of the current conditions of the roof and its related components. Photos 1 – 5. Roof under solar is not visible and therefore not part of this inspection. Patio cover is not part of this inspection. Photo 6

2. **Finding:** The utility flashing is not secured at the collar. Photo 7

Recommendation: Seal the collar as needed.

If leakage has occurred anywhere inside the home in the past beneath the current roof or if there are moisture stains beneath the roof inside the home, please inform the office before scheduling repairs as a more destructive investigation will be required (as opposed to a visible inspection) to repair damage or other deficiencies that are not visible and likely exist beneath the roof surface.

Asphalt roofing shingles generally have a service life of at least 25 – 40+ years in this area of the country, if the proper maintenance has been provided. Early signs of aging include brittleness, minor curling, and loss of mineral granules, while signs of advanced aging are severe curling, cracked or split shingles, and an exposed fiberglass base mat. As a roof approaches the end of its economic life expectancy, repairs increasingly become necessary, due to an increased likelihood of leakage in the last few years of roof life. Typical maintenance is recommended on a regular basis throughout the entire life of the roof, consisting of inspection for and the replacement of damaged, missing, or excessively deteriorated shingles and deteriorated sealant or closure at roof penetrations and transitions. Often, fasteners begin to back out of the roof and pop through the overlying shingle, necessitating shingle replacement or repair. Proper maintenance will help ensure the roof achieves or surpasses its general service life.

Cost of recommended repairs with one-year warranty*:	**$595.00**

* Does not include low slope roofs

Report # 95408

Property Address: **1731 Mountain Blvd. Oakland, CA. 94611**
Inspection Date**: 3/16/2026** Inspector: Mike Brooks

Inspection Report Images

PHOTO 1



PHOTO 2

PHOTO 3

PHOTO 4

PHOTO 5

PHOTO 6

PHOTO 7

Report # 95408

Property Address: **1731 Mountain Blvd. Oakland, CA. 94611**
Inspection Date**: 3/16/2026** Inspector: Mike Brooks

Leak Free Warranty

We will warranty this roof against leakage for a period of one year if we perform the repairs noted above or if the roof is found to be water-tight at the time of inspection, unless noted otherwise and subject to any restrictions or limitations listed in the body of this inspection report, at the discretion of the inspector. If the roof later develops covered leaks within the warranty period, the roof will be repaired under the warranty, in the manner we feel is most appropriate, at no cost to the buyer. Warranty does not cover leaks that were in an inaccessible area, such as under air conditioning units, solar pool heating systems or electrical solar panel systems, leaks caused by third parties (i.e. damage caused by fumigation company), leaks or damage caused by hail, high winds or other acts of God, abuse, lack of proper maintenance, manufacturing defects, leaks caused by or related to the gutter or drain system. Warranty does not cover leaks that occur from damaged felt paper or underlayment concealed beneath tile roofs as these waterproof membranes are not visible to inspection without removal of tiles on the roof. Warranty does not guarantee that original installation, material used or internal components are problem free, but that the roof is water-tight. The Leak Free Warranty excludes the following types of roofs: metal roofs, tar & gravel roofs, corrugated roofs, patio covers, leaks resulting from attachment of patio covers or overhangs, deck coatings, proprietary roof systems, metal or glass sun rooms, detached structures and low slope roofing materials, unless otherwise specified. Warranty excludes gutters, downspouts, drainage systems and interior damage caused by leaks. Workmanship on re-roofs is warranted against for a period of five years and gutter repair and gutter installation workmanship for a period of one year. We do not warrant roof materials. Roof material warranties vary based on the type of product and are issued by the manufacturer.

This report is viable for 3 months after the inspection has been performed. If repairs are needed after the 3 month period, we will need to re-inspect the roof for additional damage that may have occurred since our previous inspection.

Work Authorization

THERE IS A $595.00 MINIMUM CHARGE FOR ANY WORK AUTHORIZATION CONTRACT. SIGNED WORK AUTHORIZATION CONTRACT MUST BE RECEIVED BEFORE WORK WILL BE SCHEDULED. WORK AUTHORIZATION MAY BE EMAILED TO REPAIRS@SPECIALTYTEAM.COM. Inspection fee is billed separately from any work costs.

DISCLAIMER: Specialty Inspections assumes no responsibility for any additional work the building department may require beyond what is outlined in the scope of work. The property owner and/or the person(s) who authorize work assume responsibility for any additional work and associated costs.

LIEN NOTICE UNDER THE MECHANICS' LIEN LAW. (California Civil Code Section 3110 et seq.) Any contractor, subcontractor, laborer, supplier of any other person who helps to improve your property but is not paid for his work or supplies, has a right to enforce a claim against your property. This means that at a court hearing, your property can be sold by a court official and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your own contractor in full, if the subcontractor or laborer or supplier remains unpaid. This section constitutes pre-lien notice under the Mechanics Lien Law, Civil Code Section 3097.

WORK DONE OUTSIDE OF ESCROW REQUIRES A 40% DEPOSIT. THE TOTAL AMOUNT OF WORK AUTHORIZED IS DUE AND PAYABLE UPON COMPLETION OF THE WORK, UNLESS OTHER ARRANGEMENTS ARE MADE WITH OUR OFFICE. AT 90 DAYS FROM COMPLETION, 1.5 % INTEREST PER MONTH IS CHARGED, RETROACTIVELY, ON PAST DUE ACCOUNTS. THIS IS AN ANNUAL PERCENTAGE RATE OF 18%. ANY WORK PERFORMED AGAINST AN EXISTING TITLE ESCROW WILL BE THE FINANCIAL RESPONSIBILITY OF THE PARTY SIGNING THE AUTHORIZATION CONTRACT.

I have read and understand this work authorization contract and roof inspection report it refers to and hereby agree to all terms thereof.

Signature

Authorized signature for Specialty Inspections

Relationship to property

Acceptance Date

Who should we contact to schedule work? (name & phone)

Important: Please provide billing and scheduling information. Provide title company information if work is to be paid in escrow.

Title Company (Name & Address)

Who is paying for repairs? (Name, address, phone & email)

Escrow Officer (Name & Phone)

Close of Escrow (Date)

ROOFER	START DATE	FINISH DATE	PHOTOS	WARRANTY	COST OF WORK
	/ /	/ /	Y/N	Y/N	$

Docusign Envelope ID: 07D426A8-D8D2-43AA-A1A2-8909B8E4A602

INVOICE

SPECIALTY INSPECTIONS
HOME • TERMITE • ROOF • CHIMNEY • POOL

261 Spring Street
Pleasanton, CA 94566
Tel: (925) 249-9611
Fax: (925) 249-9511
www.specialtyteam.com

DATE	REPORT #	ESCROW #	PROPERTY LOCATION
03/17/2026	**95408**		**1731 Mountain Blvd, Oakland CA 94611**

TO: **Kyle Peacock**
1731 Mountain Blvd
Oakland, CA 94611

03/16/2026	Roof Inspection	$195.00
03/17/2026	Payment	-$195.00
	Balance Due:	**$0.00**

RETAIN THIS COPY FOR YOUR RECORDS

If you would like to leave us a positive review on Yelp, please deduct $25 from your total bill!

DUE UPON RECEIPT

1.5% per month charged on all past due accounts. This is an annual percentage rate of 18%

(Interest charged persuant to the Robinson-Patman Act)

NOTICE: "Under the Mechanics'Lien law, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property but is not paid for his work or supplies, has the right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your own contractor in full, if the subcontractor, laborer, or supplier remains unpaid."_

THANK YOU FOR YOUR BUSINESS