

5501 S IH 35 Frontage Rd

Austin 78744

Phone: 5123776850

TX Texas

US United States

Repair Order #: 79625

Tag #: 2936

Invoice Date: **09/29/2022**

Advisor: CHARLES REEVES

124844

Order Open Date : 09/26/2022

Customer Information

JADEN RILEY 3809 SPICEWOOD SPRINGS RD AUSTINTX78759 Customer Number - 44232

Home Phone #: 5127136630 Cell Phone #: 5127136630

Business Phone #:

Vehicle Information

2012BMW4DR SDN 328I RWD

VIN #: WBA3A5C57CF256942

Color #:

Advisor No. #:

Mileage #: 94390

Job # 1 Labor Total: \$ 0.00

COMPLIMENTARY MULTI-POINT INSPECTION. RESULTS CAN BE EMAILEDAND/OR PRINTED FOR CUSTOMER CONVENIENCE

Cause:

Correction: COMPLETED COMPLIMENTARY MULTI-POINT INSPECTION

Part Number Part Description Parts Total: \$ 0.00

G.O.G. & Supplies Total GOG: \$ 0.00

Qty Item Description Total

Job # 1 Total: \$ 0.00

Job # 2 Labor Total: \$ 0.00

CUSTOMER REQUEST PRICE QUOTE FOR THE IDRIVE SCREEN-CRACKED-CHECK AND ADVISE

Cause:

Correction: decliend

Part Number Part Description Parts Total: \$ 0.00

G.O.G. & Supplies Total GOG: \$ 0.00

Qty Item Description Total

Job # 2 Total: \$ 0.00

* OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.

09/30/2022 6:28 AM

~~ Thank you for your business ~~

BMW of South Austin

5501 S IH 35 Frontage Rd

Austin 78744

Phone: 5123776850

TX Texas

US United States

Repair Order #: 79625

Tag #: **2936**

Invoice Date: **09/29/2022**

Advisor: CHARLES REEVES

Advisor No. #: 124844

Order Open Date : 09/26/2022

Job # 3 Labor Total: \$ 174.95

CUSTOMER STATES THE DRIVERS SIDE HEADLAMP AND FOG LIGHTSWERE REPLACED BUT KEEPS GETTING WARNING FROM THEM- WASDAMAGED FROM COLLISION- CHECK AND ADVISE

Cause:

Correction: vehicle has aftermarket led fog lights and drivers headlightassembly has signs of attempted repair to headlight. notreplaced with a new headlightclient declined

Part Number Part Description Parts Total: \$ 0.00

G.O.G. & Supplies Total GOG: \$ 0.00

Qty Item Description Total

Job # 3 Total: \$ 174.95

Job # 4 Labor Total: \$ 0.00

CUSTOMER REQUEST A PRICE QUOTE FOR THE DRIVERS SEAT LEATHERTO BE REPLACED- CHECK AND ADVISE

Cause:

Correction: declined

Part Number Part Description Parts Total: \$ 0.00

G.O.G. & Supplies Total GOG: \$ 0.00

Qty Item Description Total

Job # 4 Total: \$ 0.00

Job # 5 **Labor Total: \$ 174.95**

CUSTOMER STATES THE BUTTON ON THE REAR TRUNK TO OPEN IT ISNOT WORKING- HAS TO OPEN THE TRUCK WITH THE FOB OR FROMINSIDE THE VEHICLE-CHECK AND ADVISE

Cause:

Correction: client declined replacement of defective trunk button

BMW of South Austin

5501 S IH 35 Frontage Rd

Austin 78744

Phone: 5123776850

TX Texas

US United States

Repair Order #: 79625

Tag #: 2936

Invoice Date: **09/29/2022**

Advisor: CHARLES REEVES

Advisor No. #: 124844

Order Open Date : 09/26/2022

Part Number Part Description Parts Total: \$ 0.00

G.O.G. & Supplies Total GOG: \$ 0.00

Qty Item Description Total

Job # 5 Total: \$ 174.95

Sublets

Job # PO # Description

Sublet Total: \$ 0.00

Amount Totals

Total Labor: \$ 349.90
Total Parts: \$ 0.00

Total Sublet: \$ 0.00

Total G.O.G.: \$ 0.00

Misc: **\$ 0.00**

Discounts: \$ 0.00

Sales Tax: \$ 0.00

Terms and Acceptance

Customer acknowledges approval of work described in this Repair Order Summary. Any Warranties on the product sold herein are those made by the manufacturer. The seller hereby expressly disclaims all warranties, either express including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

Please look for a survey on your service experience. The manufactures survey will be sent to you by email. If you are not sure if your current email address is on file please check with your service advisor.

We're working hard to make customers for life!



09/30/2022 6:28 AM

* OEM means Original Equipment Manufacturer (factory) Parts | ** All parts are New unless specified otherwise.

~~ Thank you for your business ~~

Sep **29**



BMW SOUTH AUSTIN

Purchase

-\$349.90

Transaction Type: Debit card purchase

Purchased: Thu, Sep 29, 2022 3:10 PM

Posted: Thu, Sep 29, 2022

Appears on statement as: Debit Card Purchase - BMW SOUTH AUSTIN AUSTIN, TX US