08/03/2023

12:20 PM

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) **(512) 713-6630**

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Operation: ADRB Drive Belts All, r&r 328i 12/16

Qty	Part Number	Part Description	Part Price	Ext Price
1	BM11-28-7-618-848	RIBBED V-BELT	32.08	32.08

Misc Code	Misc Description	Ext Price
SHM	SERVICE HISTORY ADMIN	0.97
SS	SHOP SUPPLIES	12.00
	LABOR \$:	200.00
	PARTS \$:	32.08
	GOG \$:	0.00

SUBTOTAL \$: 248.77

MISC \$:

TAX \$:

12.97

3.72

08/03/2023

12:20 PM

Estimate#: RO724008 Estimate Date: 07/21/2023 Odometer: 91,906 Vehicle: F30 3 Series VIN: WBA3A5C57CF256942 License#: PVZ0755

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) **(512)** 713-6630

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Operation:6582010 Dash Control Display, r&r 12/15 W/ Navigation

Qty	Part Number	Part Description	Part Price	Ext Price
1	BM65-50-9-292-248	CENTRAL INFORMATION	3,809.81	3,809.81

Misc Code	Misc Description	Ext Price
SHM	SERVICE HISTORY ADMIN	0.97
SS	SHOP SUPPLIES	17.95

 LABOR \$:
 299.18

 PARTS \$:
 3,809.81

 GOG \$:
 0.00

 MISC \$:
 18.92

 TAX \$:
 315.87

SUBTOTAL \$: 4,443.78

08/03/2023

12:20 PM

 Estimate#: R0724008
 Estimate Date: 07/21/2023
 Odometer: 91,906

 Vehicle: F30 3 Series
 VIN: WBA3A5C57CF256942
 License#: PVZ0755

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) (512) 713-6630

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Operation:INTRIM Interior Trim Diagnosis Replace drivers seat back and bottom leather

Qty	Part Number	Part Description	Part Price	Ext Price
1	BM52-10-7-942-318	LEATHER COVER FOR BA	885.46	885.46
1	BM52-10-7-303-715	COVER, BASIC BACKRES	973.76	973.76
75	BM52-10-1-945-543	CLAMP	3.10	232.50

Misc Code	Misc Description	Ext Price
SHM	SERVICE HISTORY ADMIN	0.97
SS	SHOP SUPPLIES	46.79

LABOR \$: 779.80
PARTS \$: 2,091.72
GOG \$: 0.00
MISC \$: 47.76
TAX \$: 176.51

SUBTOTAL \$: 3,095.79

08/03/2023

12:20 PM

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) **(512)** 713-6630

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Operation: EXTRIM Exterior Trim Diagnosis Replace rear trunk button

Qty	Part Number	Part Description	Part Price	Ext Price
1	BM51-24-7-463-161	BOOT LID/TAILGATE PU	57.45	57.45

Misc Code	Misc Description	Ext Price
SHM	SERVICE HISTORY ADMIN	0.97
SS	SHOP SUPPLIES	11.70
	LABOR \$:	194.95

PARTS \$: 57.45
GOG \$: 0.00
MISC \$: 12.67
TAX \$: 5.78

SUBTOTAL \$: 270.85

08/03/2023

12:20 PM

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) **(512)** 713-6630

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Operation:6317001 Fog Lamp Assy, r&r 320i/328i/328d 12/15 Both

Qty	/ Part Number	Part Description	Part Price	Ext Price
1	BM63-17-7-248-912	FOG LIGHTS, RIGHT	262.73	262.73
1	BM63-17-7-248-911	FOG LIGHTS, LEFT	262.73	262.73

Misc Code	Misc Description	Ext Price
SHM	SERVICE HISTORY ADMIN	0.97
SS	SHOP SUPPLIES	20.72

LABOR \$: 345.35
PARTS \$: 525.46
GOG \$: 0.00
MISC \$: 21.69
TAX \$: 45.14

SUBTOTAL \$: 937.64

08/03/2023

12:20 PM

Estimate#: RO724008 Estimate Date: 07/21/2023 Odometer: 91,906
Vehicle: F30 3 Series VIN: WBA3A5C57CF256942 License#: PVZ0755

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) **(512)** 713-6630

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Operation:6312001 Headlamp Assy, r&r 12/15 Halogen LH

Qty	Part Number	Part Description	Part Price	Ext Price
1	BM63-11-7-338-709	HEADLIGHT LEFT	871.99	871.99

Misc Code	Misc Description	Ext Price
SHM	SERVICE HISTORY ADMIN	0.97
SS	SHOP SUPPLIES	41.57
	LABOR \$:	692.76

PARTS \$: 871.99
GOG \$: 0.00
MISC \$: 42.54
TAX \$: 75.45

SUBTOTAL \$: 1,682.74

08/03/2023

12:20 PM

Estimate#: RO724008 Estimate Date: 07/21/2023 Odometer: 91,906
Vehicle: F30 3 Series VIN: WBA3A5C57CF256942 License#: PVZ0755

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) **(512)** 713-6630

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Operation:6452020 A/C Compressor W/ Clutch, r&r (ADD Evacuate & Recharge) 328i 12/16

Qty	Part Number	Part Description	Part Price	Ext Price
1	BM64-52-9-216-466	AIR COND.COMPRESSOR	1,669.47	1,669.47
1	BM64-50-8-375-741	GASKET RING	11.22	11.22
1	BM64-53-8-375-742	GASKET RING	15.24	15.24

Misc Code	Misc Description	Ext Price
SHM	SERVICE HISTORY ADMIN	0.97
SS	SHOP SUPPLIES	26.27

SUBTOTAL \$:	2,303.12
TAX \$:	142.16
MISC \$:	27.24
GOG \$:	0.00
PARTS \$:	1,695.93
LABOR \$:	437.79

ESTIMATE TOTAL \$:	12,849.68
TOTAL TAX \$:	754.49
TOTAL MISC \$:	60.92
TOTAL GOG \$:	0.00
TOTAL PART \$:	9,084.44
TOTAL LABOR \$:	2,949.83

08/03/2023

12:20 PM

 Estimate#: R0724008
 Estimate Date: 07/21/2023
 Odometer: 91,906

 Vehicle: F30 3 Series
 VIN: WBA3A5C57CF256942
 License#: PVZ0755

Customer#: 189545 JADEN RILEY Advisor#: 246 CHARLES BELLINGER

Address: 3805 SPICEWOOD SPRINGS RD

#251 (H) **(512) 713-6630**

AUSTIN, TX 78759 (B) (Ext)

CUSTOMER QUOTE

Customer Signature