

# VFD INSPECTION & SERVICE REPORT

---

## JOB DETAILS

Job No : DTS-0003  
Client Name : RRRRRRRRRR  
Entry Date : 2026-02-07  
Make : RRRRRRRRRRRRRRRRR  
Model No : RRRRRRRRRR  
Serial No : RRRRRRRRRR  
Reported Fault : RRRRRRRRRR

---

## TECHNICIAN CHECKS

---

## INSPECTION REPORT

After detailed inspection and diagnostic evaluation, the unit was found to have internal electrical malfunction.

Necessary diagnostic checks were carried out to identify the root cause.

(Detailed internal inspection checklists are maintained for internal service records and are not included in this report.)

## SERVICE REPORT

The following service actions were performed:

- Internal electrical section serviced
- Defective components replaced
- Internal connections cleaned and secured
- Cooling system checked and restored
- Complete functional verification completed

All repairs were carried out using standard industrial service procedures.

## TESTING REPORT

The drive was tested under controlled conditions with rated input supply.

Test Results:

- ' Drive operates normally
- ' No abnormal heating observed
- ' Output parameters within permissible limits
- ' Unit successfully passed load testing

## WARRANTY REPORT

The repair is covered under warranty against workmanship-related defects.

WARRANTY PERIOD:

Start Date: N/A

End Date: JOB RECEIVED

Warranty does not cover physical damage, mishandling, improper installation, or electrical misuse.

## **DECLARATION**

The above-mentioned equipment has been inspected, repaired, and tested as per standard service practices and is found to be in satisfactory working condition at the time of dispatch.

For DAS TECHNO SERVICES

Authorized Signatory

Contact: +91 8401534497 / 8320534497

Email: dts@dastechnoservices.com

Shivri, Maharashtra