## Creating a Control Chart

Data Science for Quality Management: Process Control and Control Charts with Wendy Martin

#### Learning objectives:

Describe the 7 step process to create a control chart

Explain rational subgrouping

## Identify the Variable / Characteristic To Be Assessed / Monitored

- Establish requirements (Customer input or Business)
- Measurable
  - Perform Measurement System Studies

## Identify the Variable / Characteristic To Be Assessed / Monitored

 Determine whether the measurement process is generating Attribute or Variables Data

#### 2. Design the Sampling Plan

- Who Collects the Data?
- How?
- Where?
- How Often?
- Sample Size?

#### Who Will Collect the Data?

- Operator, Technician, or Other Process
  Owner
- One Shift or All Shifts
- One Station or All Stations
- Sampling and Measurement Plan
- Training
- Clear Responsibility

## How Should the Data Be Collected?


- Rational Subgroup
  - Independent specimens sampled from the same process

# How Should the Data Be Collected?

Within subgroup (common-cause)
 variation is used to determine expected
 between subgroup variation when the
 process is stable


### **Rational Subgrouping**

Measurement Value



Time

#### **Rational Subgrouping**




#### **Process Stream Effect Activity**

Method 1 – Data File is Example 1
 Method 1

Method 2 - Data File is Example 1
 Method 2


#### Example 1, Method 1



#### Example 1, Method 2

 Subgroup consists of measurements from only each stream separately

#### Example 1, Method 2



#### Sources

The material used in the PowerPoint presentations associated with this course was drawn from a number of sources. Specifically, much of the content included was adopted or adapted from the following previously-published material:

- Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982
- Luftig, J. Advanced Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1984.
- Luftig, J. A Quality Improvement Strategy for Critical Product and Process Characteristics. Luftig & Associates, Inc. Farmington Hills, MI, 1991
- Luftig, J. Guidelines for Reporting the Capability of Critical Product Characteristics. Anheuser-Busch Companies, St. Louis, MO. 1994
- Spooner-Jordan, V. Understanding Variation. Luftig & Warren International, Southfield, MI 1996
- Luftig, J. and Petrovich, M. Quality with Confidence in Manufacturing. SPSS, Inc. Chicago, IL 1997
- Littlejohn, R., Ouellette, S., & Petrovich, M. Black Belt Business Improvement Specialist Training, Luftig & Warren International, 2000
- Ouellette, S. Six Sigma Champion Training, ROI Alliance, LLC & Luftig & Warren, International, Southfield, MI 2005