Data Science for Quality Management: Sampling Distributions, Error and Estimation


with Wendy Martin

Learning objectives:

Describe the concept of sampling error

Create a vector of normally distributed random numbers


Sampling Distributions and Estimation




Parameters and Statistics

	Sample	Population
Definitions	Subgroup or portion of the population chosen for evaluation or study	Collection of all items produced or considered
Characteristics	Statistics	Parameters
Size	n	N
Mean	$ar{X}$	μ
Median	$ ilde{X}$	M
Standard Deviation	S	σ
Variance	s ²	σ^2
Skewness	g_3	γ_3
Kurtosis	g_{4}	γ_4
Proportion	р	π
Rate	$ar{c}$	λ

Sampling Distributions and Statistical Inference





Creating Random Numbers in R

```
In R / Rstudio:
```

- > rnorm()
- > rexp()
- > rpois()
- > rbinom()

- Repeated samples may not be identical
- Descriptive statistics calculated from repeated sampling (with replacement) will not be exactly the same, even though the population is unchanged.

- •This is an expected phenomenon since we are not measuring all of the subjects or units for the entire population.
- •Statistical methods allow us to account for sampling error, and make appropriate decisions.

•In spite of the presence of sampling error, random sampling allow us to use sample statistics as point estimators of population parameters; however

• Even when unbiased, sample statistics will probably not exactly equal their associated true population parameters.

•An observed difference between a true parameter value and its associated sample descriptive statistic is caused by sampling error.

Sampling Error Defined

 The expected and quantifiable discrepancy between a population parameter and its associated descriptive statistic due to the sample size employed, and in the case of some descriptive statistics, the variability of the population.

Sampling Error & Probability

 Sampling Error is quantifiable using Random Sampling Distributions (RSDs).

• These distributions, like all probability distributions, are based on the principles of classical probability.

Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982

Data Science for Quality Management: Sampling Distributions, Error and Estimation

with Wendy Martin

Learning objectives:


Explore the concept of random sampling distributions in R

A RSD is the distribution of a sample statistic calculated from all possible random samples of the given (fixed) size from a given population.


A random sampling distribution is a population distribution and foundational for understanding statistical inference.

- Draw all possible random samples of size n from a given research population
- Calculate descriptive statistics for each of the samples
- Construct a distribution for each of the sampled descriptive statistics

• Each of the resultant distributions constitutes the random sampling distribution of the statistics.




RSD of the Sample Averages



RSD of the Sample Averages (from a Normally Distributed Population)

Distribution of Individuals



Distribution

Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982

Data Science for Quality Management: Sampling Distributions, Error and Estimation

with Wendy Martin

Learning objective:

Describe the Central Limit Theorem

• The mean of the RSD of means will equal the population mean, μ , even if the parent population is not normally distributed.

•As the sample size (n) increases, the RSD of the means will approach normality, regardless of the shape of the process distribution.


•Based upon this theorem, we can use sample statistics to make inferences about population parameters.

• This applies even without our knowing anything about the shape of that population other than what we can gather from the sample (in most cases).

RSD of the Means


(from a Normally Distributed Population)

Distribution of Individuals



RSD of the Means

(from an Exponentially Distributed Population)



Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982

Probability with RSDs

Data Science for Quality Management: Sampling Distributions, Error and Estimation

with Wendy Martin

Learning objective:

Estimate probability using the Random Sampling Distribution of the mean

Estimating Probability Using the RSD of the Mean

•Note that when we use the Standard Error of the Estimate to find areas on the RSD of the means, the z-score employed becomes:

Estimating Probability Using the RSD of the Mean

$$Z_{\bar{X}} = \frac{X - \mu}{\sigma_{\bar{X}}} = \frac{X - \mu}{\sigma/\sqrt{n}}$$

•A process has historically manufactured parts at a mean, μ, of 1.325, with a standard deviation, σ, of 0.045.

•Drawing a random sample of 25 units, what is the probability of finding an \bar{X} of 1.433 or more for the sample if no change has occurred in the mean or dispersion of the process?



$$\sigma_{\bar{X}} = \frac{\sigma}{\sqrt{n}} = \frac{0.045}{\sqrt{25}} = 0.009$$

$$Z_{\bar{X}} = \frac{\bar{X} - \mu}{\sigma_{\bar{X}}} = \frac{1.433 - 1.325}{0.009} = 12$$

 The probability associated with this Z score is....really, really small!

•A process has historically manufactured parts at a mean, μ, of 50, with a standard deviation, σ, of 14.4.

•Drawing a random sample of 16 units, what is the probability of finding an \bar{X} of 55 or more for the sample if no change has occurred in the mean or dispersion of the process?



$$\sigma_{\bar{X}} = \frac{\sigma}{\sqrt{n}} = \frac{14.4}{\sqrt{16}} = 3.6$$

$$Z_{\bar{X}} = \frac{X - \mu}{\sigma_{\bar{X}}} = \frac{55 - 50}{3.6} = 1.389$$

•The probability associated with this Z score = 0.0824

RSD Examples

Statistic	RSD	Standard Error
$ar{X}$	RSD of the mean	of the mean
\widetilde{X}	RSD of the median	of the median
p	RSD of the proportion	of the proportion
R	RSD of the range	of the range

Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982

Estimates and Estimators

Data Science for Quality Management: Sampling Distributions, Error and Estimation

with Wendy Martin

Learning objectives:

Describe types of estimates

List the criteria for "good" estimators

Types of Estimates

Point Estimate

 A single number used to estimate an unknown parameter

Types of Estimates

Interval Estimate

 A range of values used to estimate a population parameter

Types of Estimates

Estimator

• A sample statistic used to estimate a population parameter. An estimate is a specific observed value of a statistic.

- Unbiased
- Efficient
- Consistent
- Sufficient

Unbiasedness

• The mean of the Random Sampling Distribution (RSD) of the estimator is equal to the parameter it estimates.

Efficiency

•Refers to the standard error of the statistic RSD. The most efficient estimator is the one with the smallest standard error.

Consistency

•Refers to the assumption that as n increases, the value of the statistic approaches the value of its associated population parameter.

Sufficiency

•Refers to using all possible information in the sample to estimate the corresponding parameter.

Point Estimates

Point Estimate		Population Parameter	
Sample Mean	\bar{X}	Population Mean	μ
Sample Variance	s^2	Population Variance	σ^2
Sample Proportion	p	Population Proportion	π
Sample Count	С	Population Count	λ
Sample Skewness	g_3	Population Skewness	γ_3
Sample Kurtosis	g_4	Population Kurtosis	γ_4

Point Estimates

$$\bar{X} \approx \mu$$

$$s \approx \sigma \text{ and } s^2 \approx \sigma^2$$

$$p \approx \pi$$

$$c \approx \lambda$$

Estimating σ from Multiple Samples

Average Range

$$\hat{\sigma} = \frac{\bar{R}}{d_2}$$

Median Range

$$\hat{\sigma} = rac{ ilde{R}}{ ilde{d}_2}$$

Average Standard Deviation

$$\hat{\sigma} = \frac{\bar{s}}{c_4}$$

Median Standard Deviation

$$\hat{\sigma} = \sqrt{\frac{(\tilde{s})^2}{\chi_{0.5, n-1df}}}$$

Estimating σ from Multiple Samples

Average Variance (equal sample size)

$$\hat{\sigma} = \sqrt{s^2}$$

(unequal sample size)

$$\hat{\sigma} = \sqrt{\frac{\sum_{j=1}^{k} (n_j - 1)s^2}{\sum_{j=1}^{k} (n_j - 1)}}$$

Estimating σ from Multiple Samples

Average Moving Range of the Mean

$$\hat{\sigma} = \frac{\overline{MR}_{\bar{X}}\sqrt{n}}{d_2}$$

Median Moving Range of the Means

$$\hat{\sigma} = \frac{\widetilde{M}R_{\bar{X}}\sqrt{n}}{\tilde{d}_2}$$

Standard Deviation of the Means $\hat{\sigma} = S_{\bar{X}} \sqrt{n}$

Point Estimates in RStudio

Point Estimate	In RStudio	
$ar{X}$	mean()	
S	sd()	
p	<pre>mean() # average proportion</pre>	
С	<pre>mean() # average count per unit</pre>	

Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982

Confidence Levels and Interval Estimates

Data Science for Quality Management: Sampling Distributions, Error and Estimation

with Wendy Martin

Learning objective:

Differentiate between confidence level and confidence interval

Confidence Level

- The confidence level is the probability associated with an interval estimate.
- This refers to the probability that the interval estimate includes the population parameter.

Confidence Level

- Typical confidence levels used are 90, 95, and 99%, with 95% confidence levels used most frequently
- •Alpha, α, is one minus the confidence level

Confidence Interval

• The confidence interval is the range of the estimate. The confidence interval is often expressed in standard error values


Confidence Intervals

• Confidence intervals provide a range of values in which we would expect to find the true population parameter, with a given level of confidence

Confidence Interval

•A 95% confidence interval for a population mean is the interval that has a 95% probability of the true population mean being found within it

Interval Estimation



Confidence Interval

•An interval estimate provides us a way to qualify our estimate by indicating the magnitude of the sampling error, and hence, the precision of our estimate

Confidence Interval


•To find this interval, we must look at the set of all possible parameters and assess each of those parameters for their probability of providing us with the sample statistic we observed


- A warranty group wishes to determine the mean life of batteries placed in new cars.
- A sample of 200 batteries is drawn and the mean battery life is found to be 38 months, with a standard deviation of 4 months.


• Their point estimate for the population mean is 38 months, but they also realize that sampling error is present, and they wish to quantify the uncertainty of this estimate.

• The question they must answer is what population means could have given a sample mean of 38?

RSD of the Sample Averages







Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982

Confidence Intervals for the Mean and Variance

Data Science for Quality Management: Sampling Distributions, Error and Estimation

with Wendy Martin

Learning objective:

Calculate interval estimates for the mean, variance and standard deviation

Calculating Confidence Intervals

- Confidence intervals may be calculated for various statistics
 - Mean
 - Sigma known
 - Sigma unknown
 - Standard Deviation / Variance

Means (Sigma Known)

 If the standard deviation is known, the following formula may be used

$$\mu_{CI} = \bar{X} \pm z_{\alpha/2} \frac{\sigma}{\sqrt{n}}$$

 For example, assume a sample was taken with the following characteristics

$$n = 150$$
, $\overline{X} = 20$, $s = 5$
Confidence Level Desired = 95%

 The 95% confidence interval (CI) for the mean is 19.2 to 20.8

$$\mu_{CI} = 20 \pm 1.96 \frac{5}{\sqrt{150}} = 20 \pm 0.80$$

Interval Estimate for the Mean (when σ is known)

In RStudio

- > z.test.onesample
- > z.test.onesample.simple


Means (Sigma Unknown)

 When the standard deviation is unknown, there is also uncertainty in the estimate of the standard error

 To account for this, instead of using the z distribution, we must use the t distribution

The t Distribution

- This distribution is commonly employed with small samples and an unknown population σ
- The t distribution is lower at the mean and higher at the tails than the normal distribution



The t Distribution

• The shape of the t distribution is dependent upon v, or (df), the degrees of freedom. Degrees of freedom relate to "the number of values which can be freely chosen"

The t Distribution

• The t distribution considers the fact there is error associated with the use of s, the sample standard deviation to estimate the population (σ)

 This error increases the variability of the resulting statistic, the t, relative to a standard normal distribution

Means (Sigma Unknown)

 If the standard deviation is unknown, the following formula may be used

$$\mu_{CI} = \bar{X} \pm t_{\alpha/2,(n-1)df} \frac{3}{\sqrt{n}}$$

 For example, assume a sample was taken with the following characteristics

> n = 14, \overline{X} = 15,000, s =500 Confidence Level desired = 90%

- The df are equal to n 1 or 13
- The t value corresponding to this is 1.771

$$\mu_{CI} = 15000 \pm 1.771 \frac{500}{\sqrt{14}} = 15000 \pm 236.66$$

 The 90% (CI) for the mean is 14763.35 to 15236.65

Interval Estimate for the Mean (when σ is unknown)

In RStudio

- > t.test.onesample
- > t.test.onesample.simple

Standard Deviation / Variance

 The following formula may be used to generate a confidence interval for a standard deviation

$$\sqrt{\frac{s^2(n-1)}{\chi^2_{\alpha/2,(n-1)df}}} < \sigma < \sqrt{\frac{s^2(n-1)}{\chi^2_{1-\alpha/2,(n-1)df}}}$$

Standard Deviation / Variance

 This formula assumes that the population sampled from may be approximated by the normal distribution

 For example, a process is studied for variability and a sample is drawn with the following characteristics

$$s = 10$$
 and $n = 25$
Confidence Level desired = 95%

 The 95% CI for the standard deviation is 7.81 to 13.91

$$\sqrt{\frac{10^2(24)}{39.364}} < \sigma < \sqrt{\frac{10^2(24)}{12.401}}$$

Interval Estimate for the Variance / Standard Deviation

In RStudio

- > variance.test.onesample
- > variance.test.onesample.simple

Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982

Confidence Intervals for Proportions and Poisson Counts

Data Science for Quality Management: Sampling Distributions, Error and Estimation

with Wendy Martin

Learning objective:

Calculate interval estimates for proportions and Poisson counts

Calculating Confidence Intervals

- Confidence intervals may be calculated for various statistics
 - Proportion
 - Poisson Counts

Proportion (Exact Binomial)

Many formulas exist to generate confidence intervals for proportions

lolcat uses the formula is that based on the exact binomial distribution

Proportion (Exact Binomial)

 The exact binomial confidence interval for all proportion uses quantiles from the Beta distribution

$$\pi_{Lower} = \beta(\frac{\alpha}{2}; np, n - np + 1)$$

$$\pi_{Upper} = \beta(1 - \frac{\alpha}{2}; np + 1, n - np)$$

 For example, assume a sample was taken with the following characteristics

- np = 12
- n = 100
- $\alpha = 0.05$

```
\pi_{Lower} = qbeta(0.025; 12,89) = 0.0636
```

$$\pi_{Upper} = qbeta(0.975; 13,88) = 0.2002$$

Interval Estimate for a Proportion

In RStudio

- > proportion.test.onesample.exact
- > proportion.test.onesample.exact.simple

Poisson Counts

 Even more formulas exist to generate confidence intervals for Poisson Counts

lolcat uses the formula is that based on the exact Poisson distribution

Poisson Counts

 The exact Poisson confidence interval for a Poisson Count uses the quantile values from the Gamma distribution

$$\lambda_{Lower} = \frac{G(\frac{\alpha}{2}, x)}{n}$$

$$\lambda_{Upper} = \frac{G(1 - \frac{\alpha}{2}, x + 1)}{n}$$

where $x = \lambda n$

 For example, assume a sample was taken with the following characteristics

$$n = 20$$
, $\lambda = 25.05$
Confidence Level Desired = 95%

- $\lambda = 25.05$
- n = 20
- $\lambda * n = 501$
- $\alpha = 0.05$

$$\lambda_{Lower} = qgamma(0.025; 501)/20 = 22.90$$

$$\lambda_{Upper} = qgamma(0.975; 502)/20 = 27.34$$

- $\lambda = 25.05$
- n = 20
- $\lambda * n = 501$
- $\alpha = 0.05$

$$\lambda_{Lower} = qgamma(0.025; 501)/20 = 23.24$$

$$\lambda_{Upper} = qgamma(0.975; 502)/20 = 26.97$$

Interval Estimate for Poisson Count

In RStudio

> poisson.test.onesample.simple()

Sources

 Luftig, J. An Introduction to Statistical Process Control & Capability. Luftig & Associates, Inc. Farmington Hills, MI, 1982