



Material sensitivity on section outputs — no cable
Blue border = material parameters (E_1, r, ν_{12}); index = S_T



Total-order Sobol index S_T