
The Price Display – Case Design Changes – Back panel only.

Video Preview of case Rev1 - https://photos.app.goo.gl/WDJCBhzovMo87uqf6


1. The rear legs need to move in by 0.5mm



2. Increase top height of rear legs by 0.7mm



3. Make rear screw holes a little deeper (so screw can go down further).



4. The holes for the inner centre point and size incorrect.

The computer chip (black board) holes were bigger than the 3D design provided. The holes are 2.6mm in diameter, and the centre point is 2mm in from the corner. This caused the inner screw holes to not line up correctly.

I have taken a video of this interference https://photos.app.goo.gl/WDJCBhzovMo87uqf6

