From Siemens Check-List

- 1. 1. dew point meter
- 2. baffle plates to protect drain cock
- 3. regenerative towers
- 4. releasing of brakes with rope handle
- 5. Attend the problem
- 6. closing cocks
- 7.