



## Solution to Installation Failure of MM32 USB Driver under WinXP

1. Start the device manager and uninstall the MM32 USB driver that is failed to be installed or enumerated into other devices, as shown in the following figure:











2. Open the system installation path C:\Windows\inf and delete all oem\*.inf, oem\*.PNF files;




3. Restart the computer, open my computer\properties, and set the driver signature in the hardware options of the system properties;













4. Connect MM32-LINK with PC and open the device manager as shown in the figure; decompress the Driver directory and point to it when installing the driver manually.



5. Follow the following steps to install the MM32-CDC driver;

































6. The installation steps of MM32 LINK driver is the same as that of MM32 CDC driver.



