


Step 1. Constraints are described in the **SysML requirements diagram**

Step 2. Interaction is represented through **SysML Activity Diagram**

Step 3. Main components are described using **SysML BDD diagrams**.



Step 4&5. Software and hardware architectures are represented through **SysML BDD**

Step 6. Activities are represented through **SysML sequence diagrams**

Step 7. Data flows are represented through **SysML IBD**

Step 8. Equations are represented through **SysML IBD**

