Softing.OPCToolbox.Server.
DaAddressSpaceElement.DaAddress
SpaceElement

Softing.OPCToolbox.Server. AddressSpaceElement.GetChildren

Softing.OPCToolbox.Server.

DaAddressSpaceElement.RemoveChild

Softing.OPCToolbox.Result Code.SUCCEEDED

Softing.OPCToolbox.Server.
Application.Trace