Softing.OPCToolbox.Server. TestServer.OpcServer.Prepare Application.Activate Softing.OPCToolbox.Server. Application.Initialize Softing.OPCToolbox.Server. AeCategory.AddSubConditionDefinition DemoServer.OpcServer.Build Softing.OPCToolbox.Server. **AEEventCategories** AeCategory.AddConditionDefinition BISDemo.DeviceEvent.Build Category BISDemo.DataEvent.BuildCategory Softing. OPCToolbox. Server.Application.AddAeCategory Console.OpcServer.BuildEvent DIISample.OpcServer.Build DIISample.OpcServer.Trace Categories **EventCategories** Softing.OPCToolbox.Server. Application.FireEvents DemoServer.OpcServer.Trace Console.Console.Main DemoServer.OpcServer.Build Console.OpcServer.Trace DAAddressSpace Console.OpcServer.BuildAddress Space Softing.OPCToolbox.Server. AeAddressSpaceElement.AddChild DemoServer.OpcServer.Build AEAddressSpace PerfClient.OpcServer.Trace PerfClient.OpcServer.add AddressSpaceElement Softing.OPCToolbox.Server. DaAddressSpaceElement.AddChild BISDemo.BISApplication.Build Namespace TestServer.OpcServer.Trace AddressSpace.OpcServer.Rebuild UpdateMode.OpcServer.Trace RandomAddressSpace AddressSpace.OpcServer.Build Softing.OPCToolbox.Server. AddressSpace Application.Trace Softing.OPCToolbox.Server. Application. Change Conditions TestServer.OpcServer.Build AddressSpace Softing. OPC Toolbox. Server.Ae Category. Add AttributeUpdateMode.OpcServer.Build AddressSpace Softing.OPCToolbox.Server. DaTransaction.CompleteRequest Softing.OPCToolbox.Server. Application.ChangeCondition Softing.OPCToolbox.Server.  $\label{lem:decomplete} Da Transaction. Complete Requests$ Softing.OPCToolbox.Server. AeCondition.Change BISDemo.DataPointElement. ExecuteCommand ConsoleCtt.MyTransaction. HandleReadRequests BISDemo.DeviceElement.Execute Command BISDemo.CommandElement.Handle ItemWriteRequest  ${\bf BISDemo. Command Property.}$ HandleReadRequest Softing.OPCToolbox.Server. Application.ReleaseCondition Softing. OPCToolbox. Server.Ae Address Space Element. Remove ChildSofting.OPCToolbox.Server. DaAddressSpaceElement.RemoveChild BISDemo.DaBaseElement.Simulate AddressSpace.OpcServer.Trace SerialIO.OpcServer.Trace Session.OpcServer.Trace Softing.OPCToolbox.Server. DaTransaction.ValuesChanged