

DRILL THROW ANALYSIS

Total Actual Quantity

90M

Total Rejected Quantity

5M

Total Repair Cost

3bn


Sum Of Machine failures

20K


REJECTION_RATE by batch_id




MACHINE_FAILURE_RATE by machine_id




down_time by machine_id



actual_quality by product_type



Sum of temperature_1 and Sum of vib_x_1 by machine_id



energy and energy1 by Month

