

DRILL THROUGH ANALYSIS

Total Actual Quantity

90M

Total Rejected Quantity

5M


Total Repair Cost

3bn


Sum Of Machine failures

20K


REJECTION_RATE by batch_id




MACHINE_FAILURE_RATE by machine_id



down_time by machine_id




actual_quality by product_type



product_type

- Product_8
- Product_5
- Product_19
- Product_15
- Product_6

Sum of temperature_1 and Sum of vib_x_1 by machine_id



energy and energy1 by Month

