

PLASTIC2

+0.25 / 0.00





PLASTIC

+0.25 / -1.25





PLASTIC

 $^{\mathsf{T}}$ + 0.25 / -1.25





PLASTIC2

+0.25 / -1.50





PLASTIC

-0.25 / -1.75





PLASTIC

^T -0.25 / -1.75





PLASTIC

-0.25 / -1.00





PLASTIC

+0.25 / -1.00



0.25/-1/Polv