## Pressure Measuring PH Measuring EC Measuring Passive Connectors and I2C Repeater - Bridge JP2 pins 1-2 - Let Open JP1 (EC\_MOSI) NT1 (SDA\_EC) NT2 (SCL\_EC) todo: - find an alternative for the i2c buffer