
$I=rac{1}{R}V$

Which part depends on the material we're using?

What happens if we make this very small?



Current as function of voltage for 30-40 Å grains of Al on an oxidized Al film.