

Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698

owensp4@nationwide.com

Insured: SHARON WOODS Home: (410) 800-0503

Property: 4206 ARIZONA AVE Cell: (410) 361-1170

BALTIMORE, MD 21206-3605 E-mail: woodssv50@gmail.com

Home: 4206 ARIZONA AVE

BALTIMORE, MD 21206-3605

Claim Rep.: Patrick Owensby Business: (443) 206-5698

Business: PO Box 182068 E-mail: owensp4@nationwide.com

Columbus, OH 43218-2068

Estimator: Patrick Owensby Business: (443) 206-5698

Business: PO Box 182068 E-mail: owensp4@nationwide.com

Columbus, OH 43218-2068

Claim Number: 411035-GO Policy Number: 5219HR096279 Type of Loss: WIND DAMAGE

Date Contacted: 3/28/2023 3:07 PM

Date of Loss: 8/5/2022 12:00 AM Date Received: 3/26/2023 2:00 AM Date Inspected: 4/3/2023 10:00 AM Date Entered: 3/28/2023 10:39 AM

Price List: MDBA8X_MAR23

Restoration/Service/Remodel

Estimate: SHARON_WOODS6



Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698 owensp4@nationwide.com

Dear Valued Customer,

Please refer to the attached itemized estimate. The estimate contains our valuation of the damages for the reported loss and was prepared using usual and customary prices for your geographic area. If this is a supplemental or updated estimate and your policy includes replacement cost coverage, please refer to our communication regarding how to make a claim for any additional eligible payment.

Please note that if your mortgage company is included on your claim payment check, contact the mortgage company to discuss how to handle the proceeds of this payment.

If you choose to hire a contractor or vendor to make repairs, please provide this estimate to them. If you, your contractor, or vendor determine that there are additional building fees and/or permits associated with the estimated repairs that are not included in this estimate, please contact me immediately so that I may review and make a determination as to the appropriate payment.

If you discover any additional damage to your property, please immediately contact me, either personally or through your contractor/vendor. We may need to re-inspect your property before authorization of supplemental payment. Please do not destroy or discard any of the damaged items until we have had an opportunity to inspect the damages and have reached an agreement with you on any supplemental cost.

Nationwide may also request to re-inspect your property, at your convenience, as part of our commitment to quality and customer service.

Thank you for allowing Nationwide General Insurance Company to serve your insurance needs. Please contact me at the numbers listed above if you have any questions regarding this estimate or any other matter pertaining to your claim.

ANY PERSON WHO KNOWINGLY OR WILLFULLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR PAYMENT OF A LOSS OR BENEFIT OR WHO KNOWINGLY AND WILLFULLY PRESENTS FALSE INFORMATION IN AN APPLICATION FOR INSURANCE IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN PRISON.



Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698 owensp4@nationwide.com

SHARON_WOODS6

Source - Eagle View

Source - Eagle View



Dwelling Roof

1526.66 Surface Area236.22 Total Perimeter Length

15.27 Number of Squares

QUAN	TITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
1. Tear off, haul and dispose of comp. shingles - 3 tab										
15.3	27 SQ	65.42	0.00	249.74	1,248.70	10/25 yrs	Avg.	NA	(0.00)	1,248.70
Includes: Dump fees, hauling, disposal, and labor to remove composition shingles and felt.										
2. 3 tab - 25 y	r comp. sh	ingle roofing -	w/out felt							
16.	67 SQ	296.86	118.69	1,266.84	6,334.19	10/25 yrs	Avg.	40%	(838.77)	5,495.42

This line item includes a roofing surface material allowance of \$114.64 per square, which reflects current market prices in your area. Market prices were verified by ITEL. The ITEL Material Purchase Program allows you or your contractor of choice to have materials delivered directly to your property for installation. For more information on ordering material through ITEL, contact them at customerservice@itelinc.com or 800-890-4835. Waste percentage set at 7% for gable roof due to itemization of starter and ridge cap.

Includes: 3 tab composition shingles, roofing nails, and installation labor.

3. Asphalt starter - universal starter cour	3.	Asphalt	starter -	- universal	starter	course
---	----	---------	-----------	-------------	---------	--------

53.31 LF 2.70 1.95 36.47 182.36 10/20 yrs Avg. 50% (17.24) 165.12

Starter strip is being applied to the eaves only. Starter is not REQUIRED on rake edges.

4. Hip / Ridge cap - composition shingles

28.00 LF 6.06 2.42 43.02 215.12 10/25 yrs Avg. 40% (17.10) 198.02

This line item includes a roofing surface material allowance of \$114.64 per square, which reflects current market prices in your area. Market prices were verified by ITEL. The ITEL Material Purchase Program allows you or your contractor of choice to have materials delivered directly to your property for installation. For more information on ordering material through ITEL, contact them at customerservice@itelinc.com or 800-890-4835.

5. Ice & water barrier

512.04 SF 2.11 12.29 273.17 1,365.86 0/30 yrs Avg. 0% (0.00) 1,365.86

This item replaces RFGFELT15 Roofing felt - 15 lb. or expands the scope of repairs, as required by current building codes. Settlement is based on the associated item until the code upgrade cost is incurred, subject to limits.

6. Roofing felt - 15 lb.

2.51 SQ	46.74	1.29	29.65	148.26	10/20 yrs	Avg. 50%	(11.38)	136.88
7. Roofing felt - 15 lb.								
12.76 SQ	46.74	6.55	150.74	753.69	10/20 yrs	Avg. 50%	(57.88)	695.81
8. Drip edge								
236.22 LF	3.55	16.16	213.69	1,068.43	10/35 yrs	Avg. 28.57%	(81.56)	986.87
9. Flashing - pipe jack								
2.00 EA	64.69	2.00	32.85	164.23	10/35 yrs	Avg. 28.57%	(10.09)	154.14



Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698 owensp4@nationwide.com

CONTINUED - Dwelling Roof

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
10. Chimney flashing - a	verage (32" x	36")							
1.00 EA	567.52	5.92	143.36	716.80	10/35 yrs	Avg.	28.57%	(29.86)	686.94
11. Detach & Reset Exha	ust cap - throu	igh roof - 6"	to 8"						
1.00 EA	122.36	0.05	30.61	153.02	0/35 yrs	Avg.	0%	(0.00)	153.02
12. Roofer - per hour									
2.00 HR	189.33	0.00	94.67	473.33	10/NA	Avg.	0%	(0.00)	473.33
Additional labor to work a damaged, these hours will				_	0	· •		f the damaged f	lashing. If
13. Additional charge for	high roof (2 s	stories or grea	ater)						
15.27 SQ	29.70	0.00	113.38	566.90	10/NA	Avg.	0%	(0.00)	566.90
14. Remove Additional c	harge for steep	p roof - 10/12	2 - 12/12 slope	e					
15.27 SQ	25.73	0.00	98.23	491.13	10/NA	Avg.	NA	(0.00)	491.13
15. Additional charge for	steep roof - 1	0/12 - 12/12	slope						
15.27 SQ	105.70	0.00	403.51	2,017.55	10/NA	Avg.	0%	(0.00)	2,017.55
16. Digital satellite system	m - Detach &	reset							
2.00 EA	52.45	0.00	26.23	131.13	10/NA	Avg.	0%	(0.00)	131.13
Totals: Dwelling Roof		155.03	2,932.99	14,664.84				1,063.88	13,600.96

8' 8' 8' 8' 8' 8' 8' 2' 6'' 2' 6'' 2' 6''	12'3"1_
' 11"	1' 11'
8' 4 " 8' 4" -	
Rear Bedroom	11.2
333	
9' 4"	1, 3,

Rear Bedroom Height: 8'

335.33 SF Walls133.88 SF Ceiling469.21 SF Walls & Ceiling133.88 SF Floor14.88 SY Flooring44.00 LF Floor Perimeter46.50 LF Ceil. Perimeter

Door2' 6" X 6' 8"Opens into ExteriorWindow2' 6" X 4'Opens into ExteriorWindow2' 6" X 4'Opens into Exterior

	QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
17.	Lead swab test - self	test (per sampl	e)							
	1.00 EA	17.22	0.20	4.35	21.77	10/NA	Avg.	0%	(0.00)	21.77
18.	R&R 1/2" drywall - l	hung, taped, flo	oated, ready fo	or paint						
	20.00 SF	3.45	0.85	17.47	87.32	10/150 yrs	Avg.	6.67%	(1.01)	86.31



Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698 owensp4@nationwide.com

CONTINUED - Rear Bedroom

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
19. R&R Acoustic ceilin	ng (popcorn) te	xture							
133.88 SF	1.80	0.72	60.43	302.14	10/150 yrs	Avg.	6.67%	(0.85)	301.29
20. Seal/prime then pair	nt the ceiling (2	coats)							
133.88 SF	1.06	1.69	35.90	179.50	10/15 yrs	Avg.	66.67%	(19.87)	159.63
21. Mask and prep for p	aint - plastic, p	aper, tape (pe	er LF)						
46.50 LF	1.52	0.75	17.86	89.29	10/15 yrs	Avg.	66.67%	(8.87)	80.42
22. R&R Crown moldin	ıg - 4 1/4"								
12.00 LF	7.32	2.17	22.51	112.52	10/150 yrs	Avg.	6.67%	(2.55)	109.97
23. Seal & paint crown	molding - two	coats							
46.50 LF	1.68	0.45	19.65	98.22	10/15 yrs	Avg.	66.67%	(5.26)	92.96
24. Blown-in insulation	- 6" depth - R1	3							
20.00 SF	0.81	0.53	4.18	20.91	10/150 yrs	Avg.	6.67%	(0.63)	20.28
in attic									
25. Contents - move out	then reset - La	rge room							
1.00 EA	124.47	0.00	31.12	155.59	10/NA	Avg.	0%	(0.00)	155.59
26. Clean and deodorize	carpet								
133.88 SF	0.62	0.08	20.77	103.86	10/NA	Avg.	0%	(0.00)	103.86
27. Final cleaning - cons	struction - Resi	dential							
133.88 SF	0.38	0.00	12.72	63.59	10/NA	Avg.	0%	(0.00)	63.59
28. Haul debris - per pic	kup truck load	- including d	lump fees						
0.50 EA	170.97	0.00	21.37	106.86	10/NA	Avg.	NA	(0.00)	106.86
debris haul off for bedr	coom only								
Totals: Rear Bedroom		7.44	268.33	1,341.57				39.04	1,302.53
Total: Source - Eagle V	View	162.47	3,201.32	16,006.41				1,102.92	14,903.49
Total: Source - Eagle V	View	162.47	3,201.32	16,006.41				1,102.92	14,903.49

Labor Minimums Applied

	QUANTITY	UNIT	TAX	O&P	RCV A	GE/LIFE	COND.	DEP %	DEPREC.	ACV
29. 1	Drywall labor minim	ium								
	1.00 EA	193.53	0.00	48.38	241.91	0/NA	Avg.	0%	(0.00)	241.91
30. I	Finish carpentry labo	or minimum								
	1.00 EA	186.31	0.00	46.58	232.89	0/NA	Avg.	0%	(0.00)	232.89



Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698 owensp4@nationwide.com

CONTINUED - Labor Minimums Applied

QUANTITY	UNIT	TAX	O&P	RCV	AGE/LIFE	COND.	DEP %	DEPREC.	ACV
31. Insulation labor min	imum								
1.00 EA	182.69	0.00	45.67	228.36	0/NA	Avg.	0%	(0.00)	228.36
32. Floor cleaning labor	minimum								
1.00 EA	110.81	0.00	27.70	138.51	0/NA	Avg.	0%	(0.00)	138.51
33. Cleaning labor mini	mum*								
1.00 EA	97.49	0.00	24.37	121.86	0/NA	Avg.	0%	(0.00)	121.86
Totals: Labor Minimu Applied	ms	0.00	192.70	963.53				0.00	963.53
Line Item Totals: SHA WOODS6	ARON_	162.47	3,394.02	16,969.94				1,102.92	15,867.02

^{[%] -} Indicates that depreciate by percent was used for this item

Grand Total Areas:

335.33	SF Walls	133.88	SF Ceiling	469.21	SF Walls and Ceiling
133.88	SF Floor	14.88	SY Flooring	44.00	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	46.50	LF Ceil. Perimeter
133.88	Floor Area	149.82	Total Area	335.33	Interior Wall Area
1,339.14	Exterior Wall Area	49.17	Exterior Perimeter of Walls		
1.526.66	Surface Area	15.27	Number of Squares	236.22	Total Perimeter Length
,	Total Ridge Length		Total Hip Length		

Coverage	Item Total	%	ACV Total	%
Dwelling	16,969.94	100.00%	15,867.02	100.00%
Dwelling - Code Upgrade	0.00	0.00%	0.00	0.00%
Other Structures	0.00	0.00%	0.00	0.00%
Contents	0.00	0.00%	0.00	0.00%
Total	16,969.94	100.00%	15,867.02	100.00%

[[]M] - Indicates that the depreciation percentage was limited by the maximum allowable depreciation for this item

Nationwide*

Nationwide General Insurance Company

Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698 owensp4@nationwide.com

Summary for Dwelling

Line Item Total	13,413.45
Material Sales Tax	162.47
Subtotal	13,575.92
Overhead	2,036.38
Profit	1,357.64
Replacement Cost Value	\$16,969.94
Less Depreciation	(1,102.92)
Actual Cash Value	\$15,867.02
Less Deductible	(500.00)
Net Claim	\$15,367.02
Total Recoverable Depreciation	1,102.92
Net Claim if Depreciation is Recovered	\$16,469.94

Patrick Owensby

Nationwide

Nationwide General Insurance Company

Patrick Owensby PO Box 182068 Columbus OH 43218-2068 443-206-5698 owensp4@nationwide.com

Summary for Dwelling - Code Upgrade

Line Item Total	0.00
Replacement Cost Value Net Claim	\$0.00 \$0.00
Dwelling - Code Upgrade Paid When Incurred	
Line Item Total	963.08
Material Sales Tax	11.00
Subtotal	974.08
Overhead	146.11
Profit	97.41
Replacement Cost Value	\$1,217.60
Total Paid When Incurred	\$1,217.60
Net Claim	\$0.00
Net Claim if Additional Amounts are Recovered	\$1,217.60

This estimate includes amounts to test and/or for initial containment of lead and/or asbestos. These amounts may not be covered by your policy given the absence of direct physical loss to your property caused by lead and/or asbestos and/or the application of certain policy exclusions, including those for loss resulting directly or indirectly from enforcement of an Ordinance or Law and from Contamination or Pollution. Nonetheless, as an accommodation to you, the company has agreed to pay the specified testing and/or containment costs on your behalf. In accepting this estimate and the company's payment, you agree that the company is reserving all its rights and that the payment of these testing and/or containment costs will not prejudice, waive, or affect in any way the company's ability to enforce its rights under your policy and otherwise.

For additional information related to lead and asbestos testing and containment, visit www.epa.gov/lead or www.epa.gov/asbestos.

Patrick Owensby