ALLCAT A USAA Service Provider PO BOX 33490 San Antonio, TX 78265 855-925-5228

8/17/2022

Insured: BLUM, CPT MARC Home: (410) 358-4248 Home: 2907 W STRATHMORE **Business:** (410) 576-4240

BALTIMORE, MD 21209 Cell: (410) 591-7893

2907 W STRATHMORE AVE Property: E-mail: mblum@worldtotalreturn.com BALTIMORE, MD 21209

Claim Rep.: **Braden Sims Business:** (866) 625-5228

> Cellular: (432) 559-4302

Estimator: **Braden Sims** (866) 625-5228 Business:

> Cellular: (432) 559-4302

Member Number: 003854027 **Policy Number:** 003854027/90A L/R Number: 018

Type of Loss: Hail Cause of Loss: Other

Insurance Company: United Services Automobile Association

| Coverage | Deductible | Policy Limit |
|------------------|------------|--------------|
| Dwelling | \$500.00 | \$572,000.00 |
| Contents | \$0.00 | \$429,000.00 |
| Other Structures | \$0.00 | \$57,200.00 |
| Loss of Use | \$0.00 | \$0.00 |

Date Contacted: 4/27/2022 5:00 PM

Date of Loss: 6/14/2021 2:00 AM Date Received: 4/22/2022 2:00 AM Date Inspected: 5/13/2022 10:00 AM Date Entered: 4/25/2022 11:51 AM

Date Est. Completed: 8/17/2022 1:23 PM

> Price List: MDBA8X_APR22

> > Restoration/Service/Remodel

Summary for Dwelling

| Line Item Total | 1,393.81 |
|------------------------|------------|
| Material Sales Tax | 12.94 |
| Replacement Cost Value | \$1,406.75 |
| Less Deductible | (500.00) |
| Less Prior Payment(s) | (274.80) |
| Net Claim Remaining | \$631.95 |

ALLCAT

BLUM, CPT MARC 8/17/2022 Page: 2

Braden Sims

Please contact our adjuster if you believe a supplement to this estimate is needed. Before we will consider a supplement to this estimate, we must have the opportunity to re-inspect the damages prior to the supplemental work being done.


8/17/2022

Recap of Taxes

| | Material Sales Tax (6%) | Manuf. Home Tax (6%) | Storage Tax (6%) |
|------------|-------------------------|----------------------|------------------|
| Line Items | 12.94 | 0.00 | 0.00 |
| Total | 12.94 | 0.00 | 0.00 |

BLUM_CPT_MARC11

Main Level



Roof1

1092.21 Surface Area157.14 Total Perimeter Length

10.92 Number of Squares67.13 Total Ridge Length

| Description | Quantity | Unit Price | RCV | Depreciation | ACV |
|---------------------------|---------------------------|-------------------|--------|--------------|--------|
| 1. Remove 3 tab - 25 yr | composition shingle roo | fing - incl. felt | | | |
| .33 | 0.33 SQ | 62.14 | 20.51 | (0.00) | 20.51 |
| 2. 3 tab - 25 yr comp. sh | ingle roofing - w/out fel | ţ | | | |
| .33 | 0.33 SQ | 286.57 | 94.57 | (0.00) | 94.57 |
| 3. Roofing felt - 15 lb. | | | | | |
| .33 | 0.33 SQ | 44.07 | 14.54 | (0.00) | 14.54 |
| Totals: Roof1 | | | 129.62 | 0.00 | 129.62 |

Elevations

| Description | Quantity | Unit Price | RCV | Depreciation | ACV |
|---------------------------|------------------------|-----------------------|--------|--------------|--------|
| 4. R&R Window screen, | 1 - 9 SF | | | | |
| 1 | 1.00 EA | 49.15 | 49.15 | (0.00) | 49.15 |
| 5. R&R Gutter / downspo | out - aluminum - up to | 5'' | | | |
| 10 | 10.00 LF | 9.01 | 90.10 | (0.00) | 90.10 |
| 6. R&R Wrap wood wind | low frame & trim with | aluminum sheet - Smal | 1 | | |
| 3 | 3.00 EA | 160.73 | 482.19 | (0.00) | 482.19 |
| Totals: Elevations | | | 621.44 | 0.00 | 621.44 |
| Total: Main Level | | | 751.06 | 0.00 | 751.06 |

Labor Minimums Applied

| Description | Quantity | Unit Price | RCV | Depreciation | ACV |
|--------------------------|----------|------------|--------|--------------|--------|
| 7. Roofing labor minimum | | | | | |
| 1 | 1.00 EA | 642.75 | 642.75 | (0.00) | 642.75 |

67.13 Total Ridge Length

8/17/2022

CONTINUED - Labor Minimums Applied

| Description | Quantity | | Unit Price | RCV | | Depreciation | ACV |
|---------------|----------------------|-------|-----------------------------|----------|--------|------------------------|----------|
| Totals: Labor | r Minimums Applied | | | 642.75 | | 0.00 | 642.75 |
| Line Item Tot | als: BLUM_CPT_MARC11 | | | 1,393.81 | | 0.00 | 1,393.81 |
| Grand Tota | al Areas: | | | | | | |
| 0.00 | SF Walls | 0.00 | SF Ceiling | | 0.00 | SF Walls and Ceiling | |
| 0.00 | SF Floor | 0.00 | SY Flooring | | 0.00 | LF Floor Perimeter | |
| 0.00 | SF Long Wall | 0.00 | SF Short Wall | | 0.00 | LF Ceil. Perimeter | |
| 0.00 | Floor Area | 0.00 | Total Area | | 0.00 | Interior Wall Area | |
| 68.61 | Exterior Wall Area | 0.00 | Exterior Perimeter of Walls | | | | |
| 1,092.21 | Surface Area | 10.92 | Number of Squares | | 157.14 | Total Perimeter Length | 1 |

0.00 Total Hip Length

8/17/2022

Page: 6

Recap by Room

Estimate: BLUM__CPT_MARC11

| Area: | Main Level | |
|-------|------------|--|
| | Daagt | |

| Area: Main Level | | |
|---------------------------|----------|---------|
| Roof1 | 129.62 | 9.30% |
| Elevations | 621.44 | 44.59% |
| Area Subtotal: Main Level | 751.06 | 53.89% |
| Labor Minimums Applied | 642.75 | 46.11% |
| Subtotal of Areas | 1,393.81 | 100.00% |
| Total | 1,393.81 | 100.00% |

BLUM, CPT MARC 8/17/2022 Page: 7

Recap by Category

| Items | Total | % |
|---------------------------|----------|---------|
| ROOFING | 772.37 | 54.90% |
| SIDING | 482.19 | 34.28% |
| SOFFIT, FASCIA, & GUTTER | 90.10 | 6.40% |
| WINDOW REGLAZING & REPAIR | 49.15 | 3.49% |
| Subtotal | 1,393.81 | 99.08% |
| Material Sales Tax | 12.94 | 0.92% |
| Total | 1,406.75 | 100.00% |

FREQUENTLY ASKED QUESTIONS

The FAQ's and answers below will be helpful in the claim process. If there is any conflict between these answers and the policy, your policy controls. Please read your policy.

How is my initial Dwelling payment determined?

Subject to the applicable deductible and policy conditions, Dwelling payments are generally based on the cost to repair or replace the damaged property with similar construction and for the same use on the same premises. When the cost to repair or replace the damaged dwelling exceeds \$5000, USAA will pay a portion of the claim up front (the actual cash value of the loss), and the balance (recoverable depreciation) when the repairs are complete.

How do I collect the recoverable depreciation?

Where initial payment for Dwelling loss is in the amount of Actual Cash Value, to receive additional amounts (recoverable depreciation), you must complete the actual repair or replacement of the damaged part of the property. When repair or replacement is actually completed, the policy will pay the covered additional amount you actually and necessarily incurred to repair or replace the property, but not to exceed the approved replacement cost of your claim (our cost). In no case will USAA pay more than the total amount of the actual repairs less your policy deductible.

Why is the check made out to me and someone else (or some other company)?

If your check includes the name of your mortgage company it is because we are required to include their name on our payment to you, per the mortgage clause on your policy. The check must be presented to them for their endorsement prior to submitting it to our bank for payment. Incomplete endorsements will result in the check being returned without payment. Please contact us if the mortgagee information is incorrect so that we may update that information and issue a correct payment to you.

What if I'm not going to repair or replace my damaged property using the same material?

Please contact us if you choose to repair or replace the damaged building part with a different material or type of construction from what is on our estimate. Replacement or repair differing from the original estimate could affect any replacement cost claim you are otherwise eligible to collect.

What if my contractor's estimate is different from USAA's estimate?

Show the USAA estimate to your contractor. If your contractor's estimate is higher, please contact USAA prior to starting the repairs to your home as the additional charges may not be covered.