

Connectors

Underwater connectors are a frequent point of failure on gliders. Most ground faults, and intermittent sensor dropouts trace back to a connector that was mated mis-aligned, over-torqued, or left ungreased. Correct greasing and mating technique — and a quick visual inspection of the seal — prevents the majority of these problems.

 Quick Reference

Parameter	Value
Golden rule	Grease before every mating
Tighten by	Hand only — never tools
Disconnect by	Pulling straight out, never at an angle
Related topics	Maintenance , Deployment

What This Section Covers

- **SubConn® (MacArtney)** — Greasing and mating above and below water, cleaning, thread locking, and cable bending limits.
- **IE55 (Teledyne Impulse)** — Lubrication, keyway alignment, and the inspection-slot seal check for the subminiature locking-sleeve connector.

In This Section

 **SubConn® One-Pager**

Greasing, dry- and wet-mating, cleaning, and handling for SubConn connectors.