## Deformed shape

Toggle Diagrams

- 1: Original configuration
- 2: Deformed shape
- 3: Axial force
- 4: Shear force
- 5: Bending moment
- f: Fill diagram
- v: Show values
- r: Reset camera



u\_max = 0.00000 mm @ (0.00, 0.00)

v\_max = -0.63578 mm @ (5.00, 0.00)