Briquette_Press_B_40 #NVJOB Nicholas Veselov(www.nvjob.pro) 06/25/2018 09:33:41 pm 09/17/2019 03:34:34 am

Block: Author: Created: Last Modified:

Symbol Var Type Data Type Comment

> TEMP TEMP TEMP TEMP

B V4.0

Custom program for WEIMATH Standard Series briquette press. #NVJOB Nicholas Veselov (inde pend ent de velo per) - https://nvjob.pro, http://nvjob.dxam

INPUTS

- 10.0 Power.
- 10.1 Start the program in automatic mode.
- 10.2 Stop the program in automatic mode.
- 10.3 Manual mode.
- 10.4 Vertical piston, sensor, lower position.
- 10.5 Vertical piston, sensor, upper position.
- 10.6 Horizontal piston, sensor, position retracted.
- 10.7 Horizontal piston, sensor, position extended.
- 11.0 Not involved.
- 11.1 Valve button.
- 11.2 Accident, stop.
- 11.3 Change in operating time of the screw Min time*.
- 11.4 Change in the operating time of the screw. Max. 1 me*.
- I1.5 Not involved.

OUTPUTS

- Q0.0 The engine of the hydraulic power station (star-delta).
- Q0.1 Hydroelectric power station engine (star-delta).
- Q0.2 Fan.
- Q0.3-Auger.
- Q0.4 Vertical piston, valve, up position (pushes down).
- Q0.5 Vertical piston, valve, lower position (pushes up).
- Q0.6 Horizontal piston, valve, retracts the piston.
- Q0.7 Horizontal piston, valve, extends the piston.
- Q1.0 Collet Piston.
- Q1.1 Light Bulb Start

Network 1


Power. Starting up the hydraul ic station.


Power. Starting up the nydrau it station.


10.0 M0.0 T37 OUT IN TON S RS 100 ms 11.2 +50 - PT R1 T38 TON ΙN 100 ms +650 **-** PT

Network 2

 $\mbox{Q0.0}$ and $\mbox{Q0.1}$ - $\mbox{Hydroelectric}$ power station engine (star-delta). $\mbox{Q0.2}$ - $\mbox{Fan}.$








Network 6 Reset M0.1 Q0.4 (R) Q0.5 Q0.6 (R)Q0.7 (R) Q1.0 (R) M10.0 (R) Q1.1 (R) MOV_W ΕN ENO OUT -WW10 1 - IN


Network 7


Cleaning at work


T40 - dog test, vertical piston

T41 - dogging check, horizontal piston T42 - Check Valve Horizontal Piston










Network 19 Feeds sawdust on time (works, auger) M0.3 M10.0 M0.4 T39 VW10 >=| | Network 20 Filed the sawdust (the auger is off), lowers the vertical piston T40 - dog test, vertical piston M10.0 M0.4 M0.3 T40 TON 100 ms





Network 24 The button has worked, the collet is opened M0.1 M0.3 M10.0 Q0.7 II.1 10.7 II.1 A10.0 S 1 M10.0 S 1 M10.0 S 1 T42 IN TON PT 100 ms

Network 25 $10.6\,\mathrm{and}\,10.7\,\mathrm{worked}$ (horizontal piston extended all the way), horizontal piston creeps back T41 - dogging check, horizontal piston T42 - Check Valve Horizontal Piston M0.1 M0.3 M10.0 Q0.7 10.6 T49 TON 100 ms 25.A T41 TON +80 **-** PT 100 ms Network 26 M0.1 M0.3

Network 27

I0.6 and I0.7 worked (horizontal piston extended all the way), horizontal piston creeps back





Network 28 The horizontal piston retracted, the vertical piston rises, the collet undenches. M0.3 M10.0 10.4 10.6 28.A 10.7 Q0.6 (R) Q1.0 28.A (R) M10.0 (R) ADD_I VW10 < ΕN ENO 1 IN1 OUT-VW10 VW10 - IN2