




Cannot open file
D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg.
File does not exist.

Title: Top_Sheet.SchDoc	
File: Brendon_STM32-v1.1.PrjPcb	
Date: 2/10/2024	Page Num: 1
Drawn By: Huzaifa Ali	Page Total: 4


3V3 LDO REGULATOR



BATTERY











Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.


Title: Power_Sheet.SchDoc	
File: Brendon_STM32-v1.1.PrjPcb	
Date: 2/10/2024	Page Num: 2
Drawn By: Huzaifa Ali	Page Total: 4



STM32 CONTROLLER
U2A
STM32L071V8T6
U2B
STM32L071V8T6
PA 11 and PA12 input/outputs (greyed out pins) are supplied by VDDIO2.
U2C
STM32L071V8T6
RESET
BOOT
SWD PROGRAMING
7-SEGMENT
RADIO
ENCODER
BUTTONS
BUZZER
Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.
Title: Controller_Sheet.SchDoc
File: Brendon_STM32-v1.1.PrjPcb
Date: 2/10/2024
Page Num: 3
Drawn By: Huzaifa Ali
Page Total: 4














Cannot open file
D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg.
File does not exist.

Title: Peripheral_Sheet.SchDoc	
File: Brendon_STM32-v1.1.PrjPcb	
Date: 2/10/2024	Page Num: 4
Drawn By: Huzaifa Ali	Page Total: 4