


LORAWAN MODULE



COMMS MODULE INDICATION



LoRaWAN Module indication is 0011



Replace with Male Connector

Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.

Title: LoRaWAN-Sheet.SchDoc	
File: LoRaWAN-Module-v2.0.PrjPcb	
Date: 6/17/2023	Page Num: 1
Drawn By: Huzaifa Ali	Page Total: 1