



VIN
VOUT_12V
VCC_3V3
5V_EXT
GND
U_Power-Section
Power-Section.SchDoc
VIN
VCC_3V3
5V_EXT
GND
U_Stepper-Driver
Stepper-Driver.SchDoc
MOTOR
Stepper
VIN
VOUT_12V
VCC_3V3
MOTOR
Stepper
GND
U_Connector_Section
Connector_Section.SchDoc

9-30VDC to 12V BUCK REGULATOR





VOUT_12V — P6

12V TO 5V BUCK REGULATOR




5V TO 3V3 LDO CIRCUIT






MOTOR OUT




CONTROL SIGNALS




TEST POINTS



POWER SIGNALS




STEPPER MOTOR DRIVER CIRCUIT




For best electrical and thermal performance, use a reasonable amount of solid, thermally conducting vias between the die attach pad and the ground plane. The printed circuit board should have a solid ground plane spreading heat into the board and providing for a stable GND reference. For more PCB layout Details, refer to pg 94 of Datasheet.


CONTROL SIGNALS




MOTOR OUT




PUMP CONTROL




PUMP OUT




POWER SIGNALS



SUPPORTING CIRCUITRY




ETHERCAT INPUT




Replace 330R with RC0201DR-07330RL


BOARD TO BOARD HEADER



MOTOR OUT



POWER IN



ARDUINO HEADERS

