






Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.


Title: Top-Sheet.SchDoc	
File: tracker-pro-airbnb-v1.0.PrjPcb	
Date: 7/14/2023	Page Num: 1
Drawn By: Huzaifa Ali	Page Total: 8












Power Section


Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.

Title: Power-Sheet.SchDoc	
File: tracker-pro-airbnb-v1.0.PrjPcb	
Date: 7/14/2023	Page Num: 2
Drawn By: Huzaifa Ali	Page Total: 8


BATTERY CHARGING CIRCUIT



STEP UP CONVERTER



POWER MUX PRIORITY SWITCHOVER



PWR_STAT — PWR_STAT


VBUS — VBUS
5V_PoE — 5V_PoE
5V — 5V
3V3 — 3V3
GND — GND

Charging Section


Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.

Title: Charging-Boost-Sheet.SchDoc	
File: tracker-pro-airbnb-v1.0.PrjPcb	
Date: 7/14/2023	Page Num: 3
Drawn By: Huzaifa Ali	Page Total: 8


eCO2 TVOC AQI SENSOR




SUPPPORT SENSOR TO DETECT MARIJUANA




PM2.5 ENVIRONMENT SENSOR CIRCUIT




SUPPPORT SENSOR FOR MARIJUANA




TEMP HUM PRESSURE SENSOR



SECONDARY PCB CONNECTOR





Sensors Section


Cannot open file
D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg.
File does not exist.

Title: Sensor-Sheet.SchDoc

File: tracker-pro-airbnb-v1.0.PrjPcb


Date: 7/14/2023	Page Num: 4
Drawn By: Huzaifa Ali	Page Total: 8


LEVEL SHIFTER




T0D0: Remove R8 Resistor in final production
Bring out OE to Enable the ESP to control this

1.4V to 3.6V on A-PORT and 1.65V to 5.5V on B-PORT(VCCA < VCCB)










Level Shifter Section


Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.

Title: Level_Shifter_Sheet.SchDoc	
File: tracker-pro-airbnb-v1.0.PrjPcb	
Date: 7/14/2023	Page Num: 5
Drawn By: Huzaifa Ali	Page Total: 8




















Sound Detection


Cannot open file D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg. File does not exist.

Title: Sound-Detection-Sheet.SchDoc	
File: tracker-pro-airbnb-v1.0.PrjPcb	
Date: 7/14/2023	Page Num: 6
Drawn By: Huzaifa Ali	Page Total: 8











Controller Section

Cannot open file
D:\eSpark-Consultants\eSpark-Hardware\Altium
Template\espark-consulting-group-800x300.jpg.
File does not exist.

Title: ESP32-Sheet.SchDoc	
File: tracker-pro-airbnb-v1.0.PrjPcb	
Date: 7/14/2023	Page Num: 7
Drawn By: Huzaifa Ali	Page Total: 8


Ethernet Section





Cannot open file
D:\eSpark-Consultants\eSpark-Hardware\Altium Template\espark-consulting-group-800x300.jpg.
File does not exist.

Title: Ethernet-PoE-Sheet.SchDoc	
File: tracker-pro-airbnb-v1.0.PrjPcb	
Date: 7/14/2023	Page Num: 8
Drawn By: Huzaifa Ali	Page Total: 8



Layer	Name	Material	Thickness	Constant	Board Layer Stack
	Top Overlay				
	Top Solder	Solder Resist	0.39mil	3.3	
1	Top Layer		1.38mil		
	Dielectric 2	FR-4	8.27mil	4.6	
2	Signal + GND	CF-004	0.60mil		
	Dielectric 1	FR-4	41.93mil	4.6	
3	Signal + 3v3	CF-004	0.60mil		
	Dielectric 3	FR-4	8.27mil	4.6	
4	Bottom Layer		1.38mil		
	Bottom Solder	Solder Resist	0.39mil	3.3	
	Bottom Overlay				
Total board thickness:			63.21mil		