


Cannot open file C:\Users\user\Pictures\Saved Pictures\espark-consulting-group-150x150.jpg. File does not exist.

switch-box.PrjPcb

1


1

1


1

8

Huzaifa Ali





Cannot open file C:\Users\user\Pictures\Saved Pictures\espark-consulting-group-150x150.jpg. File does not exist.	Title: switch-box.PrjPcb		
	Size: A4	Number: 1	Revision: 1
	Date: 12/25/2022	Sheet 2 of 8	
	File: C:\Users\..\USB & LDO_Section.SchDoc	Drawn By: Huzaifa Ali	





Cannot open file C:\Users\user\Pictures\Saved Pictures\espark-consulting-group-150x150.jpg. File does not exist.

Title	switch-box.PrjPcb		
Size	Number		Revision
A4	1		1
Date:	12/25/2022	Sheet 3 of	8
File:	C:\Users\..\Controller_Section.SchDoc	Drawn By:	Huzaifa Ali












Title		
Size: A4	Number	Revision
Date: 12/25/2022		Sheet of
File: C:\Users\..\Sensor_Section.SchDoc		Drawn By:




Title		
Size: A	Number	Revision
Date: 12/25/2022		Sheet of
File: C:\Users\..\Isolator_Section.SchDoc		Drawn By:





Title		
Size A4	Number	Revision
Date: 12/25/2022		Sheet of
File: C:\Users\..\Driver_Section.SchDoc		Drawn By:





Cannot open file C:\Users\user\Pictures\Saved Pictures\espark-consulting-group-150x150.jpg. File does not exist.	Title: switch-box.PrjPcb		
	Size: A4	Number: 1	Revision: 1
	Date: 12/25/2022	Sheet 7 of 8	
	File: C:\Users\..\Relay_Section.SchDoc	Drawn By: Huzaifa Ali	






































Title		
Size A	Number	Revision
Date: 12/25/2022		Sheet of
File: C:\Users\..\Connector_Section.SchDoc		Drawn By: