






eSpark Consulting Group


Title: Top-Sheet.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 1
Drawn By: Huzaifa Ali	Page Total: 8

























GPIO17 CHANGED FROM GPIO28
MISPRINT ON EAGLE SCHEMATIC




















eSpark Consulting Group


Title: Power_Section.SchDoc		
File: Powermodule-v7.0.3.PrjPcb		
Date: 21/10/2024	Page	Num: 2
Drawn By: Huzaifa Ali	Page	Total: 8








GPIO17 WAS MISPRINTED AS GPIO28
Checked it with previous design and Datasheet


























Title: Controller_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 15/10/2024	Page Num: 3
Drawn By: Huzaifa Ali	Page Total: 8




BOOT SELECT




SPI_FLASH







eSpark Consulting Group


Title: FlashMemory_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 15/10/2024	Page Num: 4
Drawn By: Huzaifa Ali	Page Total: 8















eSpark Consulting Group


Title: WiFiModule_Section.SchDoc		
File: Powermodule-v7.0.3.PrjPcb		
Date: 15/10/2024	Page	Num: 5
Drawn By: Huzaifa Ali	Page	Total: 8



























eSpark Consulting Group


Title: Connector_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 6
Drawn By: Huzaifa Ali	Page Total: 8























eSpark Consulting Group

Title: USB HUB_Section.SchDoc		
File: Powermodule-v7.0.3.PrjPcb		
Date: 21/10/2024	Page	Num: 7
Drawn By: Huzaifa Ali	Page	Total: 8



Add CR927 cell in peripherals





eSpark Consulting Group

Title: RTC_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 8
Drawn By: Huzaifa Ali	Page Total: 8