







Title: Top-Sheet.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 1
Drawn By: Huzaifa Ali	Page Total: 8























GPIO17 CHANGED FROM GPIO28
MISPRINT ON EAGLE SCHEMATIC







GPIO26_ADC0 — GPIO26_ADC0


SW1 — SW1
VOXL_EN_BUCK — VOXL_EN_BUCK
GPIO10 — GPIO10
GPIO1 — GPIO1


GPIO22, GPIO23, GPIO24, GPIO17, GPIO19, GPIO18

Power — VBAT, +5V, +3V3, GND





Title: Power_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 2
Drawn By: Huzaifa Ali	Page Total: 8








GPIO17 WAS MISPRINTED AS GPIO28
Checked it with previous design and Datasheet





















































Title: Controller_Section.SchDoc		
File: Powermodule-v7.0.3.PrjPcb		
Date: 21/10/2024	Page	Num: 3
Drawn By: Huzaifa Ali	Page	Total: 8




BOOT SELECT




SPI_FLASH







eSpark Consulting Group


Title: FlashMemory_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 4
Drawn By: Huzaifa Ali	Page Total: 8















eSpark Consulting Group


Title: WiFiModule_Section.SchDoc		
File: Powermodule-v7.0.3.PrjPcb		
Date: 21/10/2024	Page	Num: 5
Drawn By: Huzaifa Ali	Page	Total: 8

































eSpark Consulting Group


Title: Connector_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 6
Drawn By: Huzaifa Ali	Page Total: 8






















Title:	USB HUB_Section.SchDoc
File:	Powermodule-v7.0.3.PrjPcb
Date: 21/10/2024	Page Num: 7
Drawn By: Huzaifa Ali	Page Total: 8



Add CR927 cell in peripherals





eSpark Consulting Group

Title: RTC_Section.SchDoc	
File: Powermodule-v7.0.3.PrjPcb	
Date: 21/10/2024	Page Num: 8
Drawn By: Huzaifa Ali	Page Total: 8