




P1
61301021121
U1A
NORA-B100
NORA-B120-00B
U1B
NORA-B120-00B
Needle Prog.
J1
S2
S1
SKRPABE010
U4
SN74LV1T34DBVR
LED1
SK6812-EC20
TVS1
INTR_MCU
Inter_SDA
Inter_CLK
20V
3V3
5V
GND
12V
DEBUG_UART
RESET
SCL
SDA
ALERT
TWI0.SDA
TWI0.SCL
BAT.MEASURE
CTS_DEBUG
RTS_DEBUG
TX_DEBUG
RX_DEBUG
USB_D_N
USB_D_P
LED_DO
CFG1
CFG2
CFG3
DNP

USB AND POWER




USB to UART







Buck-Converter 12V




Buck-Converter 3.3V




Regulator 5V



BATTERY PACK




CHARGING AND DISCHARGING




BATTERY MANAGEMENT CIRCUIT


Analog front end IC (AFE)




I2C PULL-UP




I2C ALERT




THERMISTER




CURRENT SENSE




CHARGE AND DISCHARGE FET





Title		
Size: A2	Number	Revision
Date: 11/29/2025	Sheet of	
File: E:\a Sim Data \...Piezo_Regulator_Head_P.SchDoc		


52.00mm
47.00mm
PCB Edge
ON-OFF SWITCH
PWR
BAT
-
+
NTC
+
CON-1
CON-2
CON-3
CON-4
CON-5
CON-6
CON-7
CON-8
CON-9
CON-10
CON-11
CON-12