
I am thinking we should have rechargeable battery pack to power the remote control. We will need to embed the design form into the controller. The capacity can be determined by you based on the circuit load. Our intent is that unit should be functional for at least two hours on the battery with continuos run time of one hour.



Roll over image to zoom in



Thoughts on control options for motors?

I am aware of two options one is logging in firmware to establish max and min limits for servo motor, linear actuator and other is onboard pots to manually set limits.

Incase we need to use limit switches as feedback then should we provide jumpers to select if firmware code/pot control should dictate motors limit or if sensors should relay back as to when to stop/start?