

Crack number 1

The detected crack is on wall component in this image.

Crack density: 0.25% Crack width: 6.14 mm


Angle wrt horizontal line: 1.69 degree

Configuration: longitudinal

Position: Middle fourths of the wall Severity index for this crack: 2

Suggested corrective action: General repair but no detailed investigation

required



Crack number 2

The detected crack is on wall component in this image.

Crack density: 0.08% Crack width: 6.40 mm

Angle wrt horizontal line: 9.51 degree

Configuration: longitudinal

Position: Middle fourths of the wall Severity index for this crack: 2

Suggested corrective action: General repair but no detailed investigation

required