


- 1. CONVERT LOG DATA with MS ECXEL
- 2.
- 3. 1. open file
- 4. 2. mark column A
- 5. 3. menu DATA TEXT IN COLUMNS





CLICK ON EXTENDED

Select DECIMAL POINT



Press OK and finish!