Report for Embassy Golflinks - Cinnabar Hills

Date:24/06/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	12.22	6.93	12.9	-
TURB	5.01	5.01	5.01	-
Temp	26.83	26.74	26.92	-
BOD	5.74	5.08	6.28	-
COD	22.29	21.27	23.12	-
TSS	17.74	17.35	18.04	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	114370.90	114442.50	71.60
STP inlet	118710.40	118813.40	103.00