Report for Embassy Golflinks - Pine Valley

Date:09/08/2025

Quality Report

Parameter	Avg Value	Min Limit	Max Limit	Exceedence
ph	6.00	6	6	-
TURB	0.95	1.01	1.01	-
Temp	26.43	28.13	28.27	-
BOD	4.70	5	5	-
COD	23.48	25	25	-
TSS	3.76	4	4	-
cumulatingFlow	0.00	-	-	-
flowRate	0.00	-	-	-
energy	0.00	-	-	-
voltage	0.00	-	-	-
current	0.00	-	-	-
power	0.00	-	-	-
weight	0.00	-	-	-

No energy report available.

Water Quality Report

Station	Initial Reading	Final Reading	Consumption m3
STP outlet	134946.41	135051.59	105.18
STP inlet	128616.00	128705.70	89.70